



CASA AD Biweekly 21/2014 – 16 October 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 3 October 2014 and 16 October 2014.

Rotorcraft

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2014-0226 - Main Rotor Drive / Tail Rotor Drive - Main / Tail Rotor Gearbox Oil - Sampling / Replacement

Brantly International B-2 Series Helicopters

2014-20-16 - Main Rotor Blades - Inspection for Cracks

Below 5700 kgs

GippsAero GA8 Series Aeroplanes

PAD/GA8/8 - Engine Mount Fire Seal Washer

Beechcraft 390 Series Aeroplanes

2010-10-10 - Metal Oxide Varistor and Spark Gap Wiring

Robin Aviation Series Aeroplanes

2014-0225 - Engine - By-Pass Flap In The Engine Air Intake Box - Modification

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2007-0218R2 - Fuel - Main Fuel Pump System / Fuel Pumps - Airworthiness Limitations / Inspection / Replacement

2012-0198R1 - Fuel System - Centre Tank Fuel Pump Control Circuit - Modification

2014-0137 (Correction) - Flight Controls - Elevator Servo-Control Rod Eye-Ends - Inspection / Replacement

2014-0221 - Landing Gear - Main Landing Gear Door Actuator - Monitoring / Inspection / Replacement / Modification

Airbus A330 Series Aeroplanes

2014-0222 - Landing Gear - Main Landing Gear Bogie Beam Bore - Inspection

Airbus A380 Series Aeroplanes

2011-0041R1 - Flight Controls - Aileron and Elevator Servo Controls - Electronic Centralized Aircraft Monitoring (ECAM) and Aircraft Flight Manual (AFM) Changes / Installation Prohibition

Boeing 737 Series Aeroplanes

2014-20-06 - Honeywell Phase 3 Display Units

Boeing 747 Series Aeroplanes

2014-20-07 - Upper Deck Floor Beams - Inspection

Boeing 767 Series Aeroplanes

2014-20-02 - Wing Fuel Tank Access Doors

Boeing 777 Series Aeroplanes

2014-20-06 - Honeywell Phase 3 Display Units

2014-20-10 - Strut Forward Dry Bay - Inspection for Hydraulic Fluid Contamination

Bombardier CL-600 Series Aeroplanes

CF-2014-35 - Wings - Missing Insulation Blankets in the Upper Wing Box Area

Embraer EMB-135 and EMB-145 Series Aeroplanes

2010-06-03R1 - Auxiliary Power Unit Firewall Cracking

Fokker Services F27 Series Aeroplanes

2014-0223 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

Fokker Services F28 Series Aeroplanes

2014-0224 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

Fokker Services F50 (F27 Mk 50) Series Aeroplanes

2014-0223 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2014-0224 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PT6A Series

CF-2014-33 - Power Plant - Power Turbine Containment Ring Failure

Rolls Royce Turbine Engines - RB211 Series

2014-0227-CN - Cancelled: Engine Fuel Control - Fuel Flow Meter - Inspection