



## CASA AD Biweekly 21/2015 – 15 October 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 2 October 2015 and 15 October 2015.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

AD/ECUREUIL/57 Amdt 1 - Tail Rotor Drive Shaft Bearings - CANCELLED

#### **Airbus Helicopters (Eurocopter) AS 355 Series Helicopters**

AD/AS 355/36 Amdt 1 - Aft Section Tail Rotor Drive Shaft Bearing - CANCELLED  
2015-0202 - Fuel - FUELTRON Flowmeter - Removal

### **Below 5700 kgs**

#### **Britten-Norman Aircraft BN2 Series Aeroplanes**

2015-0199 - Navigation - Pitot / Static Pressure Head - Inspection / Test

#### **M7 Aerospace (Fairchild / Swearingen) SA226 and SA227 Series Aeroplanes**

AD/SWSA226/82 - Elevator Control Rod End Bearing - CANCELLED

#### **Piper PA-28 Series Aeroplanes**

2015-20-13 - Wing Rib - Inspection

#### **Socata (Aerospatiale) Rallye Series Aeroplanes**

2015-0203 - Landing Gear - Nose Wheel Axle and Attachment Screws - Inspection / Replacement

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2015-0205 - Navigation - Airspeed Pitot Probes - Replacement

#### **Airbus A330 Series Aeroplanes**

2015-0206 - Fuselage - Cabin and Cargo Compartments Parts - Inspection / Replacement  
2015-0207 - Doors - Forward Avionics Door Cross-Members - Inspection

#### **Airbus A380 Series Aeroplanes**

2009-0152 - Wings - Movable Flap Track Fairing - Inspection / Replacement

#### **Boeing 767 Series Aeroplanes**

2015-15-06 - Inboard Main Flap Outboard Hinge Fitting

## **Boeing 777 Series Aeroplanes**

2015-19-16 - Engine - In-flight Separation of the Engine's Aft Plug

## **Dassault Aviation Falcon 7X Series Aeroplanes**

2015-0204 - Fuselage - Lateral Engine Pylons - Stiffener Attachments to Pylon Spar 41 Assembly - Inspection / Repair

## **Piston Engines**

### **Lycoming Piston Engines**

2015-19-07 - Fuel Injection Supply Lines

## **Turbine Engines**

### **Honeywell International Turbine Engines - TPE 331 Series**

2015-18-03 - Propeller Shaft Coupling Failures

### **Rolls Royce Turbine Engines - RB211 TRENT 900 Series**

2009-0051 - Engine - HP Turbine Nozzle Guide Vane (NGV) Convex Surface - Inspection

## **Equipment**

### **Fire Protection Equipment**

G-2015-0001 - Fire Protection - Engine and APU Automatic Fire Extinguishers - Inspection / Overhaul