



CASA AD Biweekly 19/2015 – 17 September 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 4 September 2015 and 17 September 2015.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2007-0209R1 - Rotor Drive - Main Gearbox Lubrication Pump - Inspection / Replacement

Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters

2015-0186 - Main Rotor - Swashplate and Support Assembly Nuts - Inspection / Replacement

Sikorsky Aircraft Corporation S-76 Series Helicopters

2015-19-51 - Main Rotor and Tail Rotor Pushrod Assemblies - Inspection / Replacement

Above 5700 kgs

Boeing 777 Series Aeroplanes

2015-17-13 - Blockage of Forward Strut Drain Lines

Boeing 787 Series Aeroplanes

2015-17-24 - Slat Skew Detection Mechanism Assembly (DMA) Proximity Sensor

Gulfstream Aerospace G1159, G-IV and GV Series Aeroplanes

AD/G1159/21 Amdt 2 - Jumpseat Placard - Installation

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PT6A Series

AD/PT6A/28 Amdt 1 - Water Washing - CANCELLED

Rolls Royce Turbine Engines - RB211 Series

2015-0187 - Engine - Low Pressure Turbine Roller Bearing - Replacement