



## CASA AD Biweekly 11/2016 – 26 May 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 13 May and 26 May 2016.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

2016-0097R1 - Tail Rotor - Pitch Control Rod Bearing - Inspection/Replacement

#### **Kawasaki BK 117 Series Helicopters**

TCD-8660A-2016 - Main Rotor Blade Vibration Absorber - Modification

### **Below 5700 kgs**

#### **ASI Aviation (Reims) F406 Series Aeroplanes**

2016-0101 - Stabilizers - Horizontal Stabilizer Fittings - Inspection / Repair

#### **Embraer EMB-500 (Phenom 100) Series Aeroplanes**

2016-05-01 - Passenger Seat Attachment Fittings

#### **Grob-Werke G115 Series Aeroplanes**

2016-0091 - Fuselage - Rear Horizontal Stabilizer Frame - Inspection / Modification

#### **M7 Aerospace (Fairchild / Swearingen) SA226 and SA227 Series Aeroplanes**

2016-10-01 - Elevator Control System

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2016-0093 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements (SEMR) - Implementation

2016-0092 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Implementation

#### **Airbus A330 Series Aeroplanes**

2016-0086R1 - Powerplant - Engine Air Intake Cowl Assembly / Piccolo Tube - Inspection

#### **Airbus A380 Series Aeroplanes**

2016-0095 - Wings - Flap Parts - Identification / Inspection [Wrong material]

#### **Boeing 737 Series Aeroplanes**

2015-21-08 - Inspar Upper Skin Inspection

2016-10-04 - Fuselage Skin and Internal Support Structure Cracks at the Number 2 VHF Antenna Location

### **Boeing 757 Series Aeroplanes**

2016-10-05 - Section 43 and 46 - Structure - Inspection for Cracks in Fuselage Frames at Stringer S-24 and S-25

### **Boeing 777 Series Aeroplanes**

2016-10-02 - Strut Aft Fairing Lower Spar Web Structure and Heat Shield - Inspection

### **Boeing 787 Series Aeroplanes**

2016-10-09 - Powerplant - GENx-1B - Forward Engine Mount - Barrel Nut Change

### **Bombardier CL-600 Series Aeroplanes**

CF-2016-15 - Passenger Oxygen System - Incorrect Length of Passenger Oxygen Mask Lanyards

### **Bombardier DHC-8 Series Aeroplanes**

CF-2016-16 - Landing Gear - Main Landing Gear - Retract Actuator Rod End Cracking

### **Dassault Aviation Mystere-Falcon 20 and 200 Series Aeroplanes**

2016-0096 - Fuselage - Bulkhead at Frame 33 - Inspection

## **Turbine Engines**

### **Turbomeca Turbine Engines - Arriel Series**

2016-0098 - Engine Fuel & Control - Hydro-Mechanical Metering Unit - Modification