



## CASA AD Biweekly 7/2016 – 31 March 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 18 March and 31 March 2016.

### **Rotorcraft**

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2016-0060 - Main Rotor - Swashplate Assembly - Replacement / Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2016-0060 - Main Rotor - Swashplate Assembly - Replacement / Inspection

#### **Bell Helicopter Textron Canada (BHTC) and Agusta Bell 206 Series Helicopters**

CF-2016-09 - Main Rotor - Corrosion of Tension-Torsion Straps

#### **Kawasaki BK 117 Series Helicopters**

AD/GBK 117/15 Amdt 2 - Tension-Torsion Straps - CANCELLED

TCD-5126B-2016 - Airworthiness Limitations Amendment

### **Below 5700 kgs**

#### **Piper PA-31 Series Aeroplanes**

AD/PA-31/94 Amdt 2 - Fuselage Bulkhead at STA.317.5 - CANCELLED

#### **Quest Aircraft Design Kodiak Series Aeroplanes**

2016-06-06 - Elevator Control - Cushion Edging - Inspection

#### **RUAG Aerospace Dornier 228 Series Aeroplanes**

2009-0031R1 - Engine Controls - Throttle Box Assembly - Inspection

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

AD/A320/216 - IAE V2500 Engine Fan Cowl Latch - CANCELLED

2016-0056 - Flight Controls - Spoiler Elevator Computer Software Update

#### **Boeing 737 Series Aeroplanes**

AD/B737/16 Amdt 4 - Engine Flameouts - Revised Operating Technique and Modifications

2016-06-04 - Window Inspection

#### **Boeing 747 Series Aeroplanes**

AD/B747/323 Amdt 2 - Nose Wheel Well Top and Side Panel Webs and Stiffeners - CANCELLED

2016-05-12 - Stretched Upper Deck - Frame and Tension Tie - Inspection

2016-06-07 - Nose Wheel Well Top and Side Panel Webs and Stiffeners

### **Boeing 777 Series Aeroplanes**

2016-06-05 - Aft Pylon Area - Fuel Leak - Sealant Application

### **Boeing 787 Series Aeroplanes**

2016-06-08 - Engine - Cold Weather Operations Fan Ice Removal - Procedures

2016-06-10 - Pylon Structures - Fuel Leak Path Seal Installation

### **Bombardier CL-600 Series Aeroplanes**

CF-2016-08 - Flight Controls - Horizontal Stabilizer Trim Actuator - Attachment Pins and Trunnions  
Not Serialized

## **Turbine Engines**

### **Rolls Royce Turbine Engines - RB211 TRENT 900 Series**

2016-0061 - Engine - High Pressure / Intermediate Pressure Structure Oil Service Tube Buffer Sealing  
Rings - Removal and Inspection

### **Turbomeca Turbine Engines - Arriel Series**

2016-0055 - Engine - Accessory Gear Box Module M01 - Inspection / Replacement

## **Equipment**

### **Cockpit Voice and Flight Data Recording Systems**

AD/REC/1 Amdt 4 - Maintenance of Cockpit Voice Recording Systems

### **Parachute Equipment**

2016-0062 - Equipment / Furnishings - Emergency Parachute Harness - Modification

### **Radio Communication (including Emergency Transmitters and Navigation Equipment)**

AD/RAD/47 Amdt 4 - Periodic Testing of ATC Transponders