



CASA AD Biweekly 17/2016 – 18 August 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 5 August and 18 August 2016.

Rotorcraft

Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters

2016-0166-E - Main Rotor Drive - Spiral Bevel Gear - Inspection

Kawasaki BK 117 Series Helicopters

TCD-8811-2016 - Tail Rotor Transmission Housing

Below 5700 kgs

de Havilland Support (Beagle) B.121 (Pup) Series Aeroplanes

AD/BEA 121/27 Amdt 3 - Control Column Handgrip Fitting

Robin Aviation Series Aeroplanes (includes Alpha Aviation R2000 Series)

2016-0148 - Powerplant - Engine-Heated Air Intake Duct - Inspection / Replacement

Above 5700 kgs

328 Support Services Dornier 328 Series Aeroplanes

2016-0155 - Fuselage - Removal of Teledyne Telelink System - Specific Maintenance Requirements

Airbus A319, A320 and A321 Series Aeroplanes

AD/A320/193 Amdt 2 - Auxiliary Power Unit Starter and Air Intake System - CANCELLED

2016-0159 - Airborne Auxiliary Power - Auxiliary Power Unit Starter Motor and Air Intake System - Inspection / Cleaning

Boeing 737 Series Aeroplanes

2016-16-13 - Fuselage Skin at the Chem-mill Steps - Inspection

Boeing 747 Series Aeroplanes

2016-16-10 - FUSELAGE - Main Frame - STA 320 Crown Frame and Window Post #3 - Inspection and Repair

Boeing 757 Series Aeroplanes

2016-15-04 - Section 43 - Lap Splice Inspection - Stringer S-14R

Diamond Aircraft Industries DA 42 and DA 62 Series Aeroplanes

2016-0156 - Engine Exhaust - Exhaust Pipes - Replacement

Piston Engines

Continental Motors (Teledyne) Piston Engines

2016-16-12 - Cylinder Head-to-Barrel Separations and Cracked/Leaking Aluminium Cylinder Heads

Technify Motors (Thielert) Piston Engines

2010-0136R1 - Engine - Timing Chain - Replacement

Equipment

Seats and Berths

2016-0163 - Equipment / Furnishings - Cabin Attendant Seat - Modification / Replacement

2016-0164 - Equipment / Furnishings - Cabin Attendant Seat - Inspection