



CASA AD Biweekly 2/2017 – 26 January 2017

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 13 January and 26 January 2017.

Rotorcraft

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2017-0007 - Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement

Bell Helicopter Textron Canada (BHTC) 427 Series Helicopters

CF-2017-03 - Empennage Structure - Cracked Vertical Fin Skins

Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters

CF-2017-02 - Time Limits & Maintenance Checks - Life-Limited Wheeled Landing Gear Parts Not Serialized

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2011-0205R1 - Stabilizers - Tail Fin Assembly - Inspection / Replacement

2016-0255R1 - Main Rotor Drive - Main Gearbox Input Module - Replacement

Sikorsky Aircraft Corporation S-92 Series Helicopters

2017-02-51 - Tail Rotor Control Systems

Above 5700 kgs

Airbus A380 Series Aeroplanes

2017-0009 - Wings - Flaps Parts - Identification / Inspection [Improper Heat Treatment]

Boeing 767 Series Aeroplanes

2017-01-09 - Flight Deck Air Relief System Components - Modification / Replacement / Installation

Boeing 787 Series Aeroplanes

2017-01-02 - Inboard and Outboard Trailing Edge Flap Rotary Actuators - Inspection / Replacement

Bombardier DHC-8 Series Aeroplanes

CF-2013-15R2 - Propellers - In-flight Operation of Propeller in Beta Range

CF-2017-04 - Fuel System - Corrosion and Wear of Hydraflow Couplings and Sleeves, Fuel Tube End Ferrules, and Fuel Component End Ferrules

CF-2017-05 - Fuel System - Motive Flow Line Fouling and Motive Flow Line and Pressure Relief Line Broken P-Clamps

Fokker Services F28 Series Aeroplanes

2017-0008 - Airborne Auxiliary Power - Flexible Fuel Drain Line - Replacement

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2017-0008 - Airborne Auxiliary Power - Flexible Fuel Drain Line - Replacement

Turbine Engines

Rolls Royce Deutschland Turbine Engines - Tay Series

2017-0010 - Engine - High Pressure Compressor Stage 12 Rotor Disc - Replacement [Life Limit]

Safran Helicopter Engines (Turbomeca) Turbine Engines - Makila Series

2016-0016R1 - Engine - Power Turbine Module 04 Bearing Supply Swivel Union - Torque Check