

# CASA AD Biweekly 22/2022 - 3 November 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 21 October 2022 and 3 November 2022.

#### Rotorcraft

Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters 2022-0214 - Equipment / Furnishings - Emergency Life-Raft System - Inspection

### Below 5700 kgs

Daher Aerospace (Socata / Aerospatiale) TBM700 Series Aeroplanes 2013-0104R2 - Flight Controls - Flap Actuator - Inspection / Replacement

### Above 5700 kgs

# Airbus A319, A320 and A321 Series Aeroplanes

2022-0213 - Doors - Passenger Door / External Handle Mechanism - Cleaning / Lubrication

#### **Airbus A380 Series Aeroplanes**

2021-0092R1 - Pneumatic - Cross-Bleed Ducts - Inspection / Replacement

#### **Boeing 737 Series Aeroplanes**

2022-21-05 - Autothrottle - Spoiler Sensor Failure Detection

#### **Boeing 757 Series Aeroplanes**

2022-20-15 - Cracks in Fastener Holes in Center Wing Box Rear Spar, Lower Skin

#### De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes

CF-2022-59 - Maintenance Requirements Manual (MRM), Part 2 Airworthiness Limitation Items (ALI) - Introduction of New Section 7-00 - Candidate Certification Maintenance Requirements (CCMR) Limitations

#### **Embraer ERJ 170 Series Aeroplanes**

2022-04-01R1 - Electrical Harnesses W126 and W127 - Inspection for Correct Routing

#### **Fokker Services F28 Series Aeroplanes**

AD/F28/93 - F70 Main Landing Gear Pistons overhauled by Aerospace NDI Pty Ltd

# Fokker Services F100 (F28 Mk 100) Series Aeroplanes

AD/F100/98 - F100 Main Landing Gear Pistons overhauled by Aerospace NDI Pty Ltd

#### Saab 340 Series Aeroplanes

2022-0216 - Flight Controls - Stall Warning / Identification System - Modification

# **Turbine Engines**

# **CFM International Turbine Engines - LEAP-1B Series**

2022-0215 - Engine - Bearing Spring Finger Housing - Inspection