

# CASA AD Biweekly 17/2025 – 28 August 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 15 August and 28 August 2025.

### **Rotorcraft**

#### Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2025-0184 - Doors - Sliding / Plugging Cabin Doors - Inspection / Modification

#### Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2025-0187 - Fuselage - Cockpit Floors - Inspection

#### Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2025-0184 - Doors - Sliding / Plugging Cabin Doors - Inspection / Modification

#### Leonardo Helicopters (AgustaWestland) A109 Series Helicopters

2025-0142R1 - Rotors Flight Control - Cyclic Control System / Pitch and Roll Actuators Attaching Bolt - Inspection

## Leonardo Helicopters (AgustaWestland) A119 Series Helicopters

2025-0142R1 - Rotors Flight Control - Cyclic Control System / Pitch and Roll Actuators Attaching Bolt - Inspection

#### Siam Hiller Holdings (Hiller) UH-12 Series Helicopters

2025-15-02 - Main Rotor Drive Shaft - Inspection for Cracks and Installation Limitations

#### Below 5700 kgs

#### **Pilatus Aircraft PC-12 Series Aeroplanes**

2025-0182 - Equipment and Furnishings - Emergency Exit / Passenger Service Unit Trim Panel Installation - Modification

## Above 5700 kgs

#### Airbus A319, A320 and A321 Series Aeroplanes

2025-0185 - Wings - Pylon Spigot Fitting - Inspections

#### **Bombardier BD-700 Series Aeroplanes**

CF-2025-40 - Electrical Power - Protective Film Cover on Secondary Power Distribution Assemblies (SPDA) not Removed

CF-2025-41 - Equipment/Furnishings - Seats - Missing Loctite

# **Turbine Engines**

#### CFM International Turbine Engines - LEAP-1A and LEAP-1C Series

2025-0171R1 - Engine - High Pressure Turbine Rotor Stage 1 Blade - Inspection

# **Equipment**

# **Restraint Equipment**

 $2025\text{-}16\text{-}09 - Pacific Scientific Rotary Buckle Assembly P/N \ 1111475 or \ 1111548\text{-}01 - Screws - Inspection/Replacement}$