

ADs Issue AL 4/2000, 20 April 2000**CAR 1998, Part 39-105 - Lighter Than Air**

There are no amendments to the CAR 1998, Part 39-105 - Lighter Than Air series this issue.

CAR 1998, Part 39-105 - Rotorcraft

Eurocopter AS 332 (Super Puma) Series Helicopters
AD/S-PUMA/27 Amdt 1 - Main Rotor Head Blade Horn Eye Bolts

Kawasaki BK117 Series Helicopters
AD/JBK 117/17 - Main Rotor Blade Balance Weight
AD/JBK 117/6 Amdt 2 - Main Rotor Blade

CAR 1998, Part 39-105 - Below 5700 kgs

Aerospatiale (Socata) TBM 700 Series Aeroplanes
TBM 700/17 Amdt 1 - Elevator Trim Tab Fitting
Beechcraft 200 (Super King Air) Series Aeroplanes
BEECH 200/67 - Fuselage Rear Pressure Bulkhead
Cessna 170, 172, F172, Fr172 and 175 Series Aeroplanes
CESSNA 170/67 - Oil Pressure Switch
Cessna 180, 182 and Wren 460 Series Aeroplanes
CESSNA 180/80 - Oil Pressure Switch
Cessna 206 Series Aeroplanes
CESSNA 206/51 - Oil Pressure Switch
Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes
SWSA 226/85 Amdt 1 - Flight Envelope Restriction
Shorts SC7 Skyvan Series Aeroplanes
SC7/27 Amdt 1 - Fatigue Life Limitations on Aircraft Subjected to Special Flight Profiles

CAR 1998, Part 39-105 - Above 5700 kgs

Airbus Industrie A300 & A310 Series Aeroplanes
AD/AB3/150 - Landing Gear Tachometer Connection and Proximity Sensor Loom
AD/AB3/151 - Fuselage Frame FR47 Splice Fittings Between Stringers 24 and 25 RH & LH
AD/AB3/152 - Frame Feet at Fuselage FR41 to FR46
AD/AB3/153 - Escape Slides at Type A Doors
Boeing 727 Series Aeroplanes
AD/B727/144 Amdt 1 - Wing Center Section Front Spar Web
Boeing 737 Series Aeroplanes
AD/B737/131 Amdt 2 - Electrical Power
Boeing 747 Series Aeroplanes
AD/B747/220 - Body Station 1265 Edge Frame
AD/B747/221 - Lower Lobe and Main Deck Side Cargo Doors Latch Pins
AD/B747/222 - Wing Front Spar Upper and Lower Chords
Boeing 757 Series Aeroplanes
AD/B757/53 - Main Cargo Deck Side Vertical Restraints
Boeing 767 Series Aeroplanes
AD/B767/116 - Engine Primary Thrust Linkage
Cessna 560 (Citation V) Series Aeroplanes
AD/CESSNA 560/5 - AFM Icing Information and Angle of Attack Computer
Fokker F100 (F28 Mk 100) Series Aeroplanes
AD/F100/34 Amdt 2 - Stabiliser Electrical Bonding
British Aerospace (Hawker Siddeley) HS 748 Series Aeroplanes
AD/HS 748/26 - Underfloor Flying Controls Circuits Forward of STA 252
AD/HS 748/27 - Elevator Primary Stop Lever

CAR 1998, Part 39-106 - Piston Engines

There are no amendments to the CAR 1998, Part 39-106 - Piston Engines series this issue.

CAR 1998, Part 39-106 - Turbine Engines

Turbomeca Turbine Engines - Makila Series
AD/MAKILA/3 - Electronic Control Unit

CAR 1998, Part 39-107 - Equipment

Fire Protection Equipment
AD/FPE/14 - Model T1-FM 100 Fire Extinguisher
Seats and Berths
AD/SEATS/14 Amdt 1 - Avio Interiors - Series 312 Seat
Crossmember Cracking
AD/SEATS/15 - Sicma Aero Seat Passenger Seats

AACs Issue AL 4/2000, 20 April 2000**Part 1 - Airworthiness Articles**

There are no amendments to AAC Part 1 - Airworthiness Articles this issue.

Part 6 - General Advice

There are no amendments to AAC Part 6 - General Advice this issue.

Part 9 - Licensing and Examination

AAC 9-0 Issue 3 - General AME Licensing Information
AAC 9-1 Issue 10 - Aircraft Maintenance Engineer (AME) Licensing Examinations
AAC 9-4 Issue 8 - Acceptance of Training Courses Conducted by Overseas Equipment Manufacturers, Operators and Training Organisations.
AAC 9-5 Issue 6 - AME Specific Type Training Courses and Examinations Conducted by Approved Australian Operators, maintenance and Training Organisations
AAC 9-91 Issue 6 - Administration and Procedure - Aircraft Maintenance Engineer Licences - Category Airframe

AACs Issue AL 5/2000, 18 May 2000**CAO 105 - Lighter Than Air**

There are no amendments to the CAO 105 - Lighter Than Air series this issue.

CAO 105 - Rotorcraft

Bell 206 and Agusta Bell 206 Series Helicopters
AD/BELL 206/143 Amdt 2 - Tail Boom Skin
Bell Helicopter Textron Canada (BHTC) 407 Series helicopters
AD/BELL 407/1 Amdt 3 - Vne Restoration to 140 KIAS
AD/BELL 407/14 - Horizontal Stabiliser Slat

CAO 105 - Below 5700 kgs

Aerospatiale (Socata) TBM 700 Series Aeroplanes
AD/TBM 700/12 Amdt 1 - Flap Rail Fittings
Ayers Thrush (Snow) Commander Series Aeroplanes
AD/AC-SNOW/25 - MLG to Fuselage Attach Bolts
Fairchild (Swearingen) SA 226 and SA 227 Series Aeroplanes
AD/SWSA 226/68 Amdt 5 - Pitch Trim Actuator
Partenavia P68 Series Aeroplanes
AD/P68/48 - Nose Landing Gear Cracking
AD/P68/49 - Landing Gear Attach Bolts

CAO 105 - Above 5700 kgs

Airbus Industrie A300 & A310 Series Aeroplanes

AD/AB3/118 Amdt 1 - Wing Pylon Thrust and Sideload Fitting

AD/AB3/154 - Fuselage Frame 73A, Beams 5 to 7
Beechcraft 400 Series Aeroplanes
AD/BEECH 400/17 - Engine Fire Extinguisher Squib Wiring
Boeing 737 Series Aeroplanes
AD/B737/140 - Main Landing Gear Axle Flange
Boeing 747 Series Aeroplanes
AD/B747/223 - Diagonal Brace Underwing Fitting Bolts
AD/B747/224 - Upper Deck Floor Beams
Boeing 757 Series Aeroplanes
AD/B757/54 - Trailing Edge Transmission
Boeing 767 Series Aeroplanes
AD/B767/117 - Landing Gear Control Lever Module
Adjacent Wiring inspection
Bombardier (Boeing Canada) DHC-8 Series Aeroplanes
AD/DHC-8/69 - Wing/Fuselage Closing Angles
British Aerospace BAe 146 Series Aeroplanes
AD/BAe 146/66 Amdt 1 - Wing Top Skin Panels
British Aerospace BAe 4100 (Jetstream) Series Aeroplanes
AD/J41/44 - Rudder Pedal Clearance
British Aerospace BAe 3100 (Jetstream) Series Aeroplanes
AD/JETSTREAM/86 - Rudder Quadrant Support Structure
Fokker F28 Series Aeroplanes
AD/F28/45 Amdt 5 - Structural Integrity Program
Israel Aircraft Industries 1123 & 1124 (Westwind) Series Aeroplanes
AD/IAI-W/20 - Aileron Radiographic Inspection
SAAB SF340 Series Aeroplanes
AD/SF340/77 - Refuel/Defuel Panel Electrical Arcing
AD/SF340/78 - Landing Gear Electrical Circuit Breakers
CAO 106 - Piston Engines
Rotax Piston Engines
AD/ROTAX/8 - Ignition Unit Stator Assembly
CAO 106 - Turbine Engines
There are no amendments to the CAO 106 - Turbine Engines series this issue.
CAO 107 - Equipment
Instruments and Automatic Pilots
AD/INST/44 - KAP 140 and KFC 225 Autopilot Systems

AACs Issue 5/2000, 18 May 2000**Part 1 - Airworthiness Articles**

AAC 1/113 - Cessna Single Engine Piston - Jammed Aileron

Part 6 - General Advice

There are no amendments to AAC Part 6 - General Advice this issue.

Part 9 - Licensing and Examination

There are no amendments to AAC Part 9 - Licensing and Examination this issue.