

# CASA AD Biweekly 13/2022 - 30 June 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 17 June 2022 and 30 June 2022.

#### **Rotorcraft**

#### Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2022-0121 - Fire Protection - Engine Fire Control Panel - Modification

### Below 5700 kgs

#### **Cirrus Design SF50 Series Aeroplanes**

2019-08-51 - Stall Warning and Protection System (SWPS) and Electronic Stability & Protection (ESP) System

2020-03-50 - Headset Amplifier and Microphone Interface Circuit Card Assemblies

#### **Costruzioni Aeronautiche Tecnam P2012 Series Aeroplanes**

2021-0119 - Flight Controls - Trim Tab Trailing Edge - Inspection

### Above 5700 kgs

#### Airbus A319, A320 and A321 Series Aeroplanes

2022-0115 - Fuselage - Cargo Compartment Fitting Brackets, Tack and Rivet Holes - Inspection / Repair

2022-0120 - Equipment / Furnishings - 80VU Rack Attachments - Inspection / Repair

#### **Airbus A330 Series Aeroplanes**

2019-0315R1 - Fuselage - Frame 67 Stringer 44 Right Hand - Inspection

#### **Boeing 737 Series Aeroplanes**

2022-11-13 - Fuselage Skin Fasteners

#### **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2022-34 - Oxygen - Supply System Flexible Oxygen Hose Deterioration Over Time

CF-2022-35 - Time Limits / Maintenance Checks - Airworthiness Limitations - Tasks Revision

#### **Embraer ERJ 190 Series Aeroplanes**

2022-06-01 - Overwing Emergency Exit Door Lower Beam (Frame) Splice Fasteners - Inspection / Rework / Replacement

#### **Pilatus Aircraft PC-24 Series Aeroplanes**

2022-0122 - Equipment / Furnishings - Stretcher Trolley Installation - Modification (EASA STC 10067483)

# **Turbine Engines**

## **General Electric Turbine Engines - Passport Series**

2022-13-12 - Core Compartment Inspection, Core Compartment Coupling Nut Retorque and Ground Power Assurance Check