

CASA AD Biweekly 15/2021 - 29 July 2021

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 16 July and 29 July 2021.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2021-0174 - Rotorcraft Flight Manual - Supplements / One-Engine Inoperative Performance Limitations - Amendment

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2021-0168 - Indicating / Recording Systems - Control Unit - Inspection

Airbus Helicopters (Eurocopter) EC 120 Series Helicopters

2021-0168 - Indicating / Recording Systems - Control Unit - Inspection

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2021-0178 - Stabilizers - Horizontal Stabilizer - Inspection / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2021-0170 - Tail Rotor - Double Bearing - Inspection / Replacement 2021-0171 - Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement

Bell Helicopter Textron UH-1 (All Variants) Series Helicopters

2021-15-14 - Tail Boom Attach Structure

Leonardo Helicopters (AgustaWestland) A109 Series Helicopters

2021-0179 - Equipment / Furnishings - Hoist Support Assembly - Inspection

Below 5700 kgs

Diamond Aircraft Industries DA 40 Series Aeroplanes

CF-2021-24 - Cabin Equipment/Furnishings - Defective Baggage Nets

Textron Aviation (Beechcraft) 200 (Super King Air) Series Aeroplanes

AD/BEECH 200/45 Amdt 5 - Nose Gear Lower Shock Absorber Assembly

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2015-0036R3 - Fuselage - Fuselage Skin Repairs - Inspection 2021-0167 - Wings - Stringer Attachments at Rib 2 to Rib 7 - Inspection / Modification 2021-0172 - Equipment / Furnishings - 80VU Rack Attachments - Inspection / Repair 2021-0175 (Correction) - Landing Gear - Main Landing Gear Sliding Tubes - Inspection 2021-0177 - Hydraulic Power - Pylon / Engine Interface Rods - Inspection / Replacement

Airbus A330 Series Aeroplanes

2021-0173 - ELBE FLUGZEUGWERKE GmbH Passenger to Freighter Conversion - Oxygen - Courier Area Oxygen Distribution System Flexible Hoses - Inspection / Replacement

Boeing 737 Series Aeroplanes

2021-14-20 - Cabin Altitude Pressure Switches 2021-10-07 - Flight Control System Functions - Maintenance Tests

Boeing 747 Series Aeroplanes

2021-14-10 - Cargo Compartment Insulation Blankets - Inspection

Boeing 767 Series Aeroplanes

2021-15-04 - STC ST02040SE - Wiring Configuration

Boeing 777 Series Aeroplanes

2021-13-02 - Installation of Insulation Blanket 2021-13-10 - Fuel Tank Access Door Cutouts - Inspection

Bombardier BD-700 Series Aeroplanes

CF-2021-17R1 - Oxygen - Supply System Flexible Oxygen Hose - Inspection and Replacement

Turbine Engines

General Electric Turbine Engines - CF6 Series

2021-14-11 - HPT Thermal Shield - Inspection

General Electric Turbine Engines - GEnx Series

2021-13-16 - Lower Fuel Manifold Leakage

International Aero Engines AG (IAE) Turbine Engines - V2500 series

2021-14-19 - 1st and 2nd Stage HPT Disk Inspection

Rolls Royce Deutschland Turbine Engines - RB211 TRENT 900 Series

2021-0176 - Engine - Critical Parts - Removal from Service

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arrius Series

2021-0088R1 - Engine Fuel & Control - Digital Engine Control Unit - Software Update