



CASA AD Biweekly 19/2020 – 17 September 2020

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 4 September and 17 September 2020.

Rotorcraft

Bell Helicopter Textron 204 Series Helicopters

2020-19-08 - Main Rotor Hub Tension-Torsion Strap Assembly - Life Limit Reduction / Removal From Service

Bell Helicopter Textron 205 Series Helicopters

2020-19-08 - Main Rotor Hub Tension-Torsion Strap Assembly - Life Limit Reduction / Removal From Service

Bell Helicopter Textron 212 Series Helicopters

2020-19-08 - Main Rotor Hub Tension-Torsion Strap Assembly - Life Limit Reduction / Removal From Service

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2020-0192 - Electrical Power - Cable Assembly - Inspection

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2020-0191 - Equipment / Furnishings - Forward Facing Central Seat(s) - Removal

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2020-0197 - Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check / Modification

Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters

2020-0197 - Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check / Modification

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2020-0193 - Landing Gear - Main Landing Gear Sliding Tubes - Inspection / Replacement

Airbus A380 Series Aeroplanes

2020-0198 - Time Limits / Maintenance Checks - Safe Life Airworthiness Limitations Items - ALS Part 1 - Amendment

Boeing 787 Series Aeroplanes

2020-17-13 - Cabin Air Conditioning and Temperature Control System - Cabin Air Compressor Outlet Check Valve

Dassault Aviation Mystere-Falcon 50 and 900 and Falcon 900EX Series Aeroplanes

2010-0080-CN - CANCELLED: Time Limits/Maintenance Checks - Airworthiness Limitations Section - Revision

Embraer EMB-505 (Phenom 300) Series Aeroplanes

2020-09-01 - Attaching Bolts of Balance Mass Weights to Elevators - Replacement

Pilatus Aircraft PC-24 Series Aeroplanes

2020-0194 - Powerplant - Engine Attachment Hardware - Inspection / Replacement

Turbine Engines

General Electric Turbine Engines - GE90 Series

2020-18-14 - High Pressure Turbine Rotor Stage 2 Disk - Inspection / Replacement

Honeywell International Turbine Engines - ALF502 and LF507 Series

2020-18-09 - Overspeed Fuel Solenoid Valve Assembly and Fuel Filter Outlet - Inspection

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2020-0196 - Engine - High Pressure / Intermediate Pressure Bearing Support Assemblies - Removal from Service