

CASA AD Biweekly 19/2025 - 25 September 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 12 September and 25 September 2025.

Rotorcraft

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2022-0168R1 - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment - Integrated Modular Avionics - Ethernet Network - Inspection

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2022-0168R1 - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment - Integrated Modular Avionics - Ethernet Network - Inspection

2025-0174R1 - Fuselage - Rear Structure / Rear Frame - Inspection

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2022-0168R1 - No longer applies to EC175B - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment - Integrated Modular Avionics - Ethernet Network - Inspection 2025-0196 - Rotorcraft Flight Manual - Emergency Procedures Section - Amendment - Integrated Modular Avionics - Ethernet Network - Inspection / Modification

Kawasaki BK 117 Series Helicopters

TCD-10528-2025 - Rescue Winch System - Hook Damper

Leonardo Helicopters (AgustaWestland) A119 Series Helicopters

2025-0199 - Power Plant - Pneumatic Line - Check / Inspection / Replacement

Below 5700 kgs

Pilatus Aircraft PC-12 Series Aeroplanes

2025-0201 - Aeroplane Flight Manual - Section Normal Procedures / Loss of Avionics - Engine Indications During Engine Start - Amendment

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2025-0158R1 - Landing Gear - Main Landing Gear Door Actuators - Inspections

2025-0151R2 - Equipment / Furnishings - Escape Slide Inflation Reservoir Regulator Valve - Inspection / Modification

2025-0207 - Fuselage - Seat Rail Connections Nylon Bushes - Replacement

Airbus A330 Series Aeroplanes

2025-0202 - Landing Gear - Nose Landing Gear Retraction Actuator - Inspection

2025-0208 - Flight Controls - Flight Control Primary Computer - Modification

Airbus A380 Series Aeroplanes

2025-0194C1 - Flight Controls - Primary System Flight Control Computer - Modification 2025-0212 - Wings - Wing Rear Spars - Inspection

Airbus Canada BD-500 Series Aeroplanes

CF-2025-47 - Fuel Distribution - Twisted Motive Flow (MF) Flexible Fuel Line

CF-2025-48 - Equipment/Furnishings - Insulation Installation - Insufficient Overlap

ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes

2025-0205 - Fuselage - Passenger Seat Tracks - Inspection / Replacement

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2025-0205 - Fuselage - Passenger Seat Tracks - Inspection / Replacement

Boeing 767 Series Aeroplanes

2025-18-05 - Incorrect Installation of First Officer Pitot-Static Tubing - FAA STC T02040SE

Boeing 787 Series Aeroplanes

2025-18-02 - Inspection and Prohibition of Certain PSU Oxygen Panel Assemblies

Dassault Aviation Falcon 7X Series Aeroplanes

2025-0200 - Equipment / Furnishings - Passenger Seats - Modification

Dassault Aviation Mystere-Falcon 50 and 900 and Falcon 900EX Series Aeroplanes

2025-0200 - Equipment / Furnishings - Passenger Seats - Modification

Dassault Aviation Falcon 2000 Series Aeroplanes

2025-0200 - Equipment / Furnishings - Passenger Seats - Modification

Embraer EMB-135 and EMB-145 Series Aeroplanes

2025-09-02 - Revision of Airworthiness Limitations

Embraer ERJ 170 Series Aeroplanes

2020-01-02R3 (Correction 2) - Engine Pylon Lower Link Lugs - Inspection / Repair

Embraer ERJ 190 Series Aeroplanes

2020-01-02R3 (Correction 2) - Engine Pylon Lower Link Lugs - Inspection / Repair

Turbine Engines

International Aero Engines AG (IAE) Turbine Engines - V2500 series

2025-19-13 - High-Pressure Turbine 1st and 2nd Stage Hubs - Replacement

Equipment

Seats and Berths

G-2025-0005 - Acro Series 9 Passenger Seats - Equipment / Furnishings - Passenger Seats - Modification