



## CASA AD Biweekly 2/2023 – 26 January 2023

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 13 January 2023 and 26 January 2023.

### **Rotorcraft**

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2023-0006-E - Main Rotor - Swashplate Assembly - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2023-0006-E - Main Rotor - Swashplate Assembly - Inspection

### **Below 5700 kgs**

#### **Diamond Aircraft Industries DA 42 and DA 62 Series Aeroplanes**

2023-0013 - Flight Controls - Rudder Steering Bracket - Inspections / Modification

#### **Piaggio Aviation P.180 Series Aeroplanes**

2023-0007 - Stabilizers - Horizontal Stabilizer Central Box - Inspection / Repair / Replacement

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2023-0008 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment

2023-0009 - Fuselage - Cockpit Lateral Window Frames - Inspection

2023-0014 - Doors - On-board Entrance Stairs / Motoreductor Units - Replacement

2023-0019-CN - CANCELLED: Electrical Power System - ARTUS Transfo-Rectifier - Replacement

#### **Airbus A330 Series Aeroplanes**

2023-0012 - Placards and Markings - Warning Labels - Inspection

2023-0015 - Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment

#### **ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes**

2023-0010 - Landing Gear - Nose Landing Gear Drag Brace Panel - Inspection / Repair

#### **ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes**

2023-0010 - Landing Gear - Nose Landing Gear Drag Brace Panel - Inspection / Repair

#### **Boeing 727 Series Aeroplanes**

2022-25-01 - Cracking of Fastener Holes at Center Wing Box Lower Skin

#### **Bombardier BD-700 Series Aeroplanes**

CF-2023-02 - Landing Gear - Nose Landing Gear - Steering Shutoff Valve Slow to Deactivate

#### **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2023-03 - Flight Controls - Elevator and Rudder Power Control Units (PCUs) Rod End Fractures

### **Embraer ERJ 190 Series Aeroplanes**

2023-01-01 - AFM Amendment - Operational Limitations

### **Fokker Services F100 (F28 Mk 100) Series Aeroplanes**

AD/F100/24 - Stubwing Upper Skin - CANCELLED

2023-0005-CN - CANCELLED: Fuselage - Stubwing Upper Skin - Inspection / Repair

### **Gulfstream Aerospace G-1159, G-IV and GV Series Aeroplanes**

2023-02-02 - Main Landing Gear Trunnion Pin Life Limit - ALS Amendment

## **Turbine Engines**

### **GE Aviation Czech (Walter) Turbine Engines - M601, H75, H80 and H85 Series**

2023-0020 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

2023-0021 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment