



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 2/2025 – 30 January 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 17 January and 30 January 2025.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2025-0025 - Equipment / Furnishings - Emergency Release Control of Cargo-Swing Installation - Inspection

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2025-0025 - Equipment / Furnishings - Emergency Release Control of Cargo-Swing Installation - Inspection

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2025-0017R1 - Fuselage - Tail Rotor Pylon - Inspection

Below 5700 kgs

Costruzioni Aeronautiche Tecnam P2008 Series Aeroplanes

2024-0152R1 - Ignition - Advanced Start System - Deactivation

GippsAero GA8 Series Aeroplanes

AD/GA8/12 - Powerplant Instrumentation and Limitations Maintenance and Operational Manual Amendment

Laviasa (Piper) PA-25 (Pawnee) Series Aeroplanes

2024-05-01R1 - Corrosion found in the Front and Rear Spars of Wings and Cracks found in the Front Spar

Pipistrel Vertical Solutions Virus SW 121 Series Aeroplanes

2025-0023-E - Flight Controls - Flaperon Bellcrank Bolt - Inspection

Above 5700 kgs

Airbus Canada BD-500 Series Aeroplanes

CF-2025-04 - Electrical System Installation - Lavatory A Maintenance Panel - Harnesses Inadequately Secured

CF-2025-07 - Flight Controls - Horizontal Stabilizer Trim Actuator (HSTA) - Incorrect Installation of the Interface Pin in the Upper Gimbal

ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes

2025-0024 - Fire Protection - Aft Cargo Compartment Fire Extinguisher Distribution Piping - Functional Check

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2025-0024 - Fire Protection - Aft Cargo Compartment Fire Extinguisher Distribution Piping - Functional Check

Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes

CF-2025-05 - Landing Gear - Uncommanded Steering

CF-2025-06 - Auxiliary Power Unit (APU) - APU Muffler Drainage Blockage Causing Fuel Leakage Accumulation

Embraer ERJ 190 Series Aeroplanes

2025-01-01 - Computerized Airplane Flight Manual Takeoff Calculation Module

Piston Engines

BRP-Rotax Piston Engines

2025-0019-E - Engine / Electrical Power - Internal Generator - Inspection / Replacement of Oil Spray Nozzle

Turbine Engines

GE Aviation Czech (Walter) Turbine Engines - M601, H75, H80 and H85 Series

2025-0022 - Engine Fuel & Control - Fuel Control System - Additive Application

Rolls Royce Deutschland Turbine Engines - RB211 TRENT 900 Series

2025-0020R1 - Engine - Combustion Rear Inner Case Bolt - Replacement / Modification