



Australian Government  
Civil Aviation Safety Authority

## CASA AD Biweekly 20/2022 – 6 October 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 23 September 2022 and 6 October 2022.

### **Rotorcraft**

#### **Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters**

2022-0205 - Tail Rotor - Damper Bracket - Inspection

### **Below 5700 kgs**

#### **Pacific Aerospace (Found Aircraft Canada) FBA-2C Series Aeroplanes**

DCA/FBA/5 - Control Arm and Yoke Assembly Sprockets - Inspection

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2022-0204 - Landing Gear - Main Landing Gear Sliding Tube - Inspection / Replacement

#### **Airbus A330 Series Aeroplanes**

2022-0197 - Fuel - Fuel Pump - Inspection / Modification

#### **ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes**

2022-0199 - Time Limits / Maintenance Checks - Certification Maintenance Requirements and Airworthiness Limitations - Amendment

2022-0200 - Time Limits / Maintenance Checks - Certification Maintenance Requirements and Airworthiness Limitations - Amendment

#### **ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes**

2022-0201 - Time Limits / Maintenance Checks - Certification Maintenance Requirements and Airworthiness Limitations - Amendment

#### **Boeing 737 Series Aeroplanes**

2022-18-13 - Web Lap Splices in the Centre Dome Apex of Aft Pressure Bulkhead

#### **Boeing 767 Series Aeroplanes**

2022-19-04 - Clearance Between Right Stabilizer Trim Shut-off Control Wire and Elevator Control Cable

#### **Boeing 777 Series Aeroplanes**

2022-18-11 - Inspection of Wing Chords

2022-14-05\_Correction - Rudder - Rudder Control Load Loop - Excessive Freeplay Detection - Inspection

## **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2022-56 - Landing Gear - Main Landing Gear (MLG) Retract Actuator Piston Rod - Safe Life Limitation Introduction

CF-2022-54R1 - Fuselage - Forward Engine Support Frame Fuselage Station 1051.30 - Inadequate Special Detailed Inspection of the Tombstone Fitting Part Numbers MM670-36153/36154 and MM690-36153/36154

## **Turbine Engines**

### **General Electric Turbine Engines - GE90 Series**

2022-18-06 - Life Limits of Certain Rotating Components

### **Safran Helicopter Engines (Turbomeca) Turbine Engines - Arrius Series**

2022-0203 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment