



**Australian Government**  
**Civil Aviation Safety Authority**

## CASA AD Biweekly 13/2012 – 28 June 2012

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 15 June and 28 June 2012.

### **Rotorcraft**

#### **Bell Helicopter Textron 412 Series Helicopters**

2012-11-13 - Aft Crosstube - Life Limit

#### **Enstrom F-28 Series Helicopters**

2012-11-05 - Cyclic Trim System Relay Failure

#### **Eurocopter AS 332 (Super Puma) Series Helicopters**

2012-0111 - Door - Cabin Sliding and Plugging Doors - Limitation / Modification / Inspection

#### **Eurocopter EC 225 Series Helicopters**

2012-0107 - Main Rotor Drive - Main Gear Box Bevel Gear Vertical Shaft - Inspection / Limitation

2012-0111 - Door - Cabin Sliding and Plugging Doors - Limitation / Modification / Inspection

#### **Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters**

2012-0108-E - Fuselage - Frame No.9 - Inspection / Repair

### **Below 5700 kgs**

#### **TECNAM P92, P96, and P2002 Series Aeroplanes**

2012-0113 - Landing Gear - Main Landing Gear (MLG) Locknuts - Replacement

### **Above 5700 kgs**

#### **Airbus Industrie A319, A320 and A321 Series Aeroplanes**

2012-0100R1 - Nacelles/Pylons - Aft Pylon Moveable Fairing Rib 5 - Inspection / Repair

#### **Airbus Industrie A330 Series Aeroplanes**

2010-0109R1 - Flight Controls - Flight Control Primary Computer (FCPC) - Dispatch restriction and Operational Test

#### **Airbus Industrie A380 Series Aeroplanes**

2012-0105 - Equipment / Furnishings - Galley Seat Rail Fitting - Replacement

#### **Boeing 717 Series Aeroplanes**

2012-12-09 - Centre Section Ribs - Horizontal Stabiliser - Inspection

## **Boeing 737 Series Aeroplanes**

AD/B737/250 Amdt 3 - Forward Entry Door Forward and Aft Side Intercostals - CANCELLED

AD/B737/343 - Cracks in Fuselage Skin - CANCELLED

2012-12-04 - Cracking - Fuselage Skin at the Chem-mill Steps - Inspection

2012-12-05 - Fatigue Cracking - Intercostals on the Forward and Aft Sides of the Forward Entry Door Cutout - Inspection

## **Boeing 777 Series Aeroplanes**

2012-12-08 - Fuse Pin - MLG Retract Actuator - Inspection / Replacement

2012-12-19 - Ceiling Support Structure - Installation

## **Boeing 767 Series Aeroplanes**

2012-12-14 - Lower Main Sill Inner Chord of the Hatch Opening of the Overwing Emergency Exit - Inspection

## **Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes**

CF-2012-21 - Main Landing Gear Up-Lock Wear

## **British Aerospace BAe 146 Series Aeroplanes**

AD/BAe 146/125 - Centre Fuselage Top Aft Longerons at Rib '0' - CANCELLED

2012-0106 - Fuselage - Inspection of Longerons at Rib '0' - Inspection / Repair

## **Fokker F50 (F27 Mk 50) Series Aeroplanes**

2012-0109 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

## **Piston Engines**

### **Thielert Piston Engines**

2012-0112 - Engine Oil - Gearbox Oil Filling Plug - Inspection

## **Turbine Engines**

### **Turbomeca Turbine Engines - Arriel Series**

2009-0236R1 - Engine - Gas Generator 2nd Stage Turbine - Inspection / Replacement