



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 22/2013 – 31 October 2013

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 18 October 2013 and 31 October 2013.

Rotorcraft

Agusta A109 Series Helicopters

2013-0265-E - Main Rotor - Rotating Controls and Swashplate Assembly - Swashplate Support Nut - Inspection / Replacement

Agusta A119 Series Helicopters

2013-0265-E - Main Rotor - Rotating Controls and Swashplate Assembly - Swashplate Support Nut - Inspection / Replacement

Bell Helicopter Textron Canada (BHTC) 206 and Agusta Bell 206 Series Helicopters

AD/BELL 206/150 - Engine to Transmission Shaft - CANCELLED

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

AD/BELL 407/15 Amdt 1 - Engine to Transmission Shaft – CANCELLED

Bell Helicopter Textron and Agusta 412 Series Helicopters

2013-20-18 - Main Rotor Yoke - Airworthiness Limitation

Bell Helicopter Textron Canada (BHTC) 427 Series Helicopters

AD/BELL 427/3 - Kaflex Drive Shaft - CANCELLED

Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters

2012-0170R1 - Time Limits and Maintenance Checks - Tail Rotor Gearbox (TGB) Oil Level and Magnetic Chip Detector - Inspection & Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement

Sikorsky S-92 Series Helicopters

2013-19-16 - Centre Fire Extinguisher Discharge Tube

Below 5700 kgs

Aerospatiale (Socata) TBM 700 Series Aeroplanes

2013-0104R1 (Correction 2) - Flight Control - Flap Actuator - Inspection / Replacement

Pilatus Britten-Norman BN-2 Series Aeroplanes

2013-0263 - Engine Controls - Engine Control Cables - Inspection / Replacement

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

AD/A320/27 Amdt 2 - Nose Wheel Steering Control
AD/A320/56 - Centre Wing, Pressurised Floor Fittings at Frame 36 - CANCELLED
2012-0100R3 (Correction) - Nacelles/Pylons - Aft Pylon Moveable Fairing Rib 5 - Inspection / Repair
2013-0261 - Fuselage - Side Box Beam Flange in Frame 43 Area - Inspection / Repair / Modification

Airbus Industrie A330 Series Aeroplanes

AD/A330/96 - Centre Fuselage FR 40 Keel Beam Flange - CANCELLED
2013-0251 (Correction) - Flight Controls - Spoiler Servo Control / Hydraulic Locking Function - Operational Test
2013-0256 - Windows - Fixed Windows / Windshield Heating Connectors - Inspection / Replacement

AMD Falcon 50 and 900 Series Aeroplanes

2013-0255 - Landing Gear - Main Landing Gear Brake Hoses - Inspection / Modification

Boeing 747 Series Aeroplanes

2013-21-03 - Elevator Control System - Inboard Elevator Power Control Actuator (PCA) - Inspection
2013-20-14 - Fuselage - Body Station 2598 Bulkhead Inner Chord and Web Cracking - Inspection / Repair

Dassault Aviation Falcon 2000 Series Aeroplanes

2013-0255 - Landing Gear - Main Landing Gear Brake Hoses - Inspection / Modification

Embraer EMB-135 and EMB-145 Series Aeroplanes

2013-10-02 - Cockpit Windshield - Lower Eyelet Fitting - Inspection / Correction

Embraer ERJ-170 Series Aeroplanes

2013-11-01 - Engine Bleed Air Precooler

Fokker F28 Series Aeroplanes

2013-0249 - Fuel - Crossfeed System - Modification

SAAB SF340 Series Aeroplanes

2013-0253 - Flight Controls - Stall Warning/Identification System Stick Pusher Rigging - Inspection / Adjustment
2013-0254 - Flight Controls - Stall Warning / Identification System / Ice Speed Curves - Deactivation

Equipment

Propellers - Variable Pitch - Hamilton Standard

2013-16-10 (Correction) - Propeller Corrosion - Calendar time inspections in Maintenance Schedule

Turbochargers

2013-21-02 - Hartzell Turbocharger Turbine Wheel Removal