



## **CASA AD Biweekly 18/2014 – 4 September 2014**

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 22 August 2014 and 4 September 2014.

### **Rotorcraft**

#### **Bell Helicopter Textron and Agusta 412 Series Helicopters**

2014-0188 - Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement) Limitation

#### **Eurocopter AS 332 (Super Puma) Series Helicopters**

2014-0188 - Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement) Limitation

#### **Eurocopter BK 117 Series Helicopters**

2014-0188 - Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement) Limitation

#### **Eurocopter EC 225 Series Helicopters**

2014-0188 - Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement) Limitation

#### **Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters**

2014-0188 - Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement) Limitation

### **Below 5700 kgs**

#### **DH 60 (Moth) Series Aeroplanes**

AD/DH 60/9 Amdt 1 - Lateral Fuselage Tie Rods - Removal and Replacement

#### **Embraer EMB-110 (Bandeirante) Series Aeroplanes**

2014-09-01 - Rudder Trim Tab Actuator

#### **Robin Aviation Series Aeroplanes**

DCA/R2000/35A - Engine Air Intake Box and Ducting - Inspection

### **Above 5700 kgs**

#### **Airbus Industrie A330 Series Aeroplanes**

2011-0173R1 - Power Plant - Engine Air Inlet Cowl Acoustic Panels - Inspection

### **Airtractor 800 Series Aeroplanes**

2014-16-17 - Wing Main Spar Lower Caps/Centre Splice Joint - Inspection

### **Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes**

CF-2014-27R1 - Wings - Inboard Flap Hinge Box - Missing Fastener Head on Forward Attachment Fitting

### **Equipment**

#### **Seats and Berths**

2014-0187 - Equipment & Furnishings - Safety Belt Attachment Bolts - Inspection / Replacement