



## CASA AD Biweekly 17/2015 – 20 August 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 7 August 2015 and 20 August 2015.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2015-0167 - Doors - Sliding / Plugging Cabin Doors - Limitation / Modification / Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2015-0163 - Doors - Jettison System Adhesive Seal - Removal

2015-0166 - Main Rotor - Swashplate Assembly - Replacement / Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2015-0166 - Main Rotor - Swashplate Assembly - Replacement / Inspection

#### **Airbus Helicopters (Eurocopter) EC 225 Series Helicopters**

2015-0167 - Doors - Sliding / Plugging Cabin Doors - Limitation / Modification / Inspection

#### **Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters**

CF-2015-16R1 - Tail Rotor - Pitch Link Spherical Bearing Accelerated Wear

### **Below 5700 kgs**

#### **Robin Aviation Series Aeroplanes (includes Alpha Aviation R2000 Series)**

DCA/R2000/43 - Wing Structure and Fuselage Attachment - Revised Airworthiness Limitations

#### **Viking Air DHC-2 (Beaver) Series Aeroplanes**

CF-2015-21 - Flight Controls - Elevator Control System - Corrosion of the Elevator Control Rod and Elevator Actuating Lever on the Control Column

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2015-0117 (Correction) - Oxygen - Chemical Oxygen Generators - Replacement

2015-0164 - Equipment / Furnishings - Overhead Stowage Compartment Attachments - Modification

2015-0026R1 - Wings - Wing Bottom Skin at Main Landing Gear Rib 5 - Inspection

2015-0170 - Electric and Electronic Common Installation - Cockpit Panel Bracket - Inspection

#### **Airbus A380 Series Aeroplanes**

2014-0153R1 - Wings - Movable Flap Track Fairing (MFTF) #6 - Inspection / Replacement / Modification

## **Boeing 737 Series Aeroplanes**

AD/B737/23 Amdt 3 - Forward Service Doorway Aft Frame - CANCELLED  
2015-16-01 - Air Conditioning - Cabin Altitude Warning System

## **Bombardier DHC-8 Series Aeroplanes**

CF-2015-24 - Ice and Rain Protection - Engine Air Intake Heater Thermostats Corrosion

## **Dassault Aviation Falcon 50 and 900 Series Aeroplanes**

2015-0165 - Exhaust - Thrust Reverser Doors Attachment Lugs - Inspection / Replacement

## **Turbine Engines**

### **Honeywell International Turbine Engines - TPE 331 Series**

2015-12-04 (Correction 2) - Fuel Control Unit Drive Spline

### **Rolls Royce Turbine Engines - RB211 TRENT 700 Series**

2015-0105R1 - Engine - High / Intermediate Pressure Turbine Bearing Support Oil Feed Tube Sealing Sleeve - Inspection / Replacement

### **Rolls Royce Turbine Engines - Viper Series**

2015-0127R1 - Time Limits / Maintenance Checks - Engine Critical Parts - Reduction of Cyclic Life Limits

### **Turbomeca Turbine Engines - Arriel Series**

2015-0162 - Engine - Accessory Gear Box Module M01 - Inspection / Replacement

## **Equipment**

### **Cockpit Voice and Flight Data Recording Systems**

AD/REC/1 Amdt 2 - Maintenance of Cockpit Voice Recording Systems