



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 18/2016 – 1 September 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 19 August and 1 September 2016.

Lighter Than Air

Hot Air Balloons

2016-17-04 - Fuel - Burner and Fuel Hoses - Identification / Replacement (Applicable to FAA Type Certificated balloons only)

Rotorcraft

AgustaWestland A109 Series Helicopters

2016-0173-E - Tail Rotor Drive - Blade Retention Bolts - Inspection / Replacement [Retirement Life Reduction]

AgustaWestland A119 Series Helicopters

2016-0173-E - Tail Rotor Drive - Blade Retention Bolts - Inspection / Replacement [Retirement Life Reduction]

Below 5700 kgs

Cessna 310 Series Aeroplanes

2016-17-08 - Elevator Trim Tab Push Pull Rod - Hardware Replacement / Inspection

Cessna 320 Series Aeroplanes

2016-17-08 - Elevator Trim Tab Push Pull Rod - Hardware Replacement / Inspection

Cessna 340 Series Aeroplanes

2016-17-08 - Elevator Trim Tab Push Pull Rod - Hardware Replacement / Inspection

Cessna 400 Series Aeroplanes

2016-17-08 - Elevator Trim Tab Push Pull Rod - Hardware Replacement / Inspection
Above 5700 kgs

328 Support Services Dornier 328 Series Aeroplanes

2016-0169 - Fuel - Fuel Line Clamps - Inspection / Replacement

Airbus A319, A320 and A321 Series Aeroplanes

2016-0176 - Airborne Auxiliary Power - Auxiliary Power Unit Starter Motor and Air Intake System - Inspection / Cleaning

Airbus A330 Series Aeroplanes

2015-0124R2 - Flight Controls - Flight Control Primary Computer - Modification / Replacement

Airbus A380 Series Aeroplanes

2016-0175 - Pneumatic - Duct Assembly Material - Replacement

Boeing 737 Series Aeroplanes

2016-18-01 - Main landing Gear Trunnion Pin Assemblies - Lubrication / Inspection / Replacement

Boeing 767 Series Aeroplanes

2016-17-06 - Aft Pressure Bulkhead Web - Inspection for Widespread Fatigue Damage

Boeing 777 Series Aeroplanes

2016-17-10 - Main Landing Gear Aft Trunnion Pin - Replacement

2016-18-02 - Oxygen - Passenger Oxygen System - Low-Pressure Oxygen Flex Hoses Replacement

Boeing 787 Series Aeroplanes

2016-17-11 - Engine Pylon Wiring Bracket - Corner Relief Fillet - Inspection

Bombardier DHC-8 Series Aeroplanes

CF-2016-25 - Fire Protection - Inadvertent Discharge of Multiple Fire Extinguishing Bottles

Dassault Aviation Falcon 2000 Series Aeroplanes

2016-0168 - Ice and Rain Protection - Air Inlet Anti-Ice System - Inspection / Repair

Equipment**Compressed Gas Cylinders**

AD/GAS/1 Amdt 11 - Inspection, Test and Retirement

Seats and Berths

2016-0167 - Equipment / Furnishings - Rear Cabin Attendant Seat - Inspection / Repair