



CASA AD Biweekly 4/2016 – 18 February 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 5 February and 18 February 2016.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2013-0133-CN - CANCELLED: Tail Rotor - Tail Rotor Hub Pitch Horn - Inspection / Replacement

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2013-0133-CN - CANCELLED: Tail Rotor - Tail Rotor Hub Pitch Horn - Inspection / Replacement

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2012-0085R6 - Main Rotor System - Main Rotor Hub - Inspection / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2016-0028 - Equipment / Furnishing - Internal Life Rafts - Inspection

Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters

CF-2016-01R1 - Tail Rotor - Pitch Link Corrosion

Below 5700 kgs

Mitsubishi MU-2 Series Aeroplanes

TCD-8678-2016 - Propeller Pitch Control (PPC) Lever Bolt Replacement

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2014-0221R1 - Landing Gear - Main Landing Gear Door Actuator - Monitoring / Inspection / Replacement / Modification

2016-0010R1 - Powerplant - Aft Engine Mount Retainers - Inspection / Replacement

Airbus A380 Series Aeroplanes

2014-0016R2 - Wings - Wing Inboard Leading Edge Droop Nose Gooseneck - Inspection / Repair / Replacement

2015-0141R1 - Wings - Leading Edge Shear Cleats - Inspection / Replacement

Boeing 737 Series Aeroplanes

2016-03-01 - Nacelle Outboard Side Load Fitting - Inspection

Bombardier CL-600 Series Aeroplanes

CF-2016-03R1 - Flight Controls - Flap and Slat Torque Tube Corrosion

Learjet 31 Series Aeroplanes

91-03-08 - Fluorescent Lighting Inverters
92-19-12 - Crew Oxygen Plumbing and Map Light Wire Protection
95-20-03 - Outflow/Safety Valve
98-06-28 - Auxiliary Cabin Heater Wiring
99-16-03 - Horizontal Stabilizer Anti-Ice System
99-23-19 - Spoiler Actuators
2001-07-11 - Main Landing Gear Tyre
2004-03-08 - Forward Engine Beam Shear Web
2005-13-36 - Aileron Control Cables
2007-04-18 - Standby Fuel Pump Annunciators
2007-17-17 - Engine Firewall

Turbine Engines

Turbomeca Turbine Engines - Arriel Series

2016-0004 (Correction) - Engine Fuel & Control - Hydro-Mechanical Metering Unit - Inspection

Equipment

Parachute Equipment

2016-0026 - Equipment / Furnishings - Emergency Parachute Rubber Bands - Replacement