



## CASA AD Biweekly 12/2016 – 9 June 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 27 May and 9 June 2016.

### **Rotorcraft**

#### **AgustaWestland A109 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement

#### **AgustaWestland AB139 and AW139 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement  
2016-0104-E (Correction) - Flight Prohibition

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

AD/ECUREUIL/22 Amdt 6 - Tail Rotor Blade Assembly - CANCELLED  
2014-0114R1 - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection / Repair

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement

#### **Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement

#### **Airbus Helicopters (Eurocopter) EC 225 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement  
2016-0104-E (Correction) - Flight Prohibition

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement

#### **Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters**

2015-0226R3 - Equipment / Furnishings - Hoist - Test / Replacement

#### **Kawasaki BK 117 Series Helicopters**

TCD-8733-2016 - Hydraulic Module Plate Assembly  
TCD-8201C-2016 - Goodrich Rescue Hoist Assembly

## **Below 5700 kgs**

### **ASI Aviation (Reims) F406 Series Aeroplanes**

AD/F406/5 - Horizontal Stabiliser Rear Attach Structure - CANCELLED

### **Piper PA-31 Series Aeroplanes**

2016-08-18 (Correction) - Inspection of the Fuel Hose Assembly and Turbocharger Support Assembly Clearance

## **Above 5700 kgs**

### **Airbus A319, A320 and A321 Series Aeroplanes**

2016-0105 - Fuselage - Cabin Floor Beam Junction - Inspection

2016-0106 - Fuselage - Frame 35.2A - Inspection

### **Airbus A330 Series Aeroplanes**

2016-0102 (Correction) - Fuselage - Fuselage Bulk Cargo Door Frames - Inspection / Repair

2016-0107 - Hydraulic Power - Hydraulic Reservoir Fluid Level - Inspection

2016-0108 - Landing Gear - Main Landing Gear Bogie Beam - Inspection / Repair / Modification

### **Boeing 737 Series Aeroplanes**

2016-11-04 - Forward Cargo Compartment Frames and Frame Reinforcements

### **Boeing 757 Series Aeroplanes**

2016-11-06 - Fuel Shutoff Valve Wire Bundle Chafing

### **Boeing 777 Series Aeroplanes**

2016-11-03 - Fuel Scavenge System

2016-11-07 - Engine Strut

### **Boeing 787 Series Aeroplanes**

2016-11-17 - Left Wing Spoiler Actuator Wire Chafing

2016-11-18 - Landing Gear - Main and Nose Landing Gear - Pin Inspection and Replacement

### **Bombardier CL-600 Series Aeroplanes**

CF-2016-17 - Wings - Life Limit Introduction for Side Brace Fitting Shaft Installed on Main Landing Gear (MLG)