



**Australian Government**  
**Civil Aviation Safety Authority**

## CASA AD Biweekly 25/2016 – 8 December 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 25 November and 8 December 2016.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

2016-0240 - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2015-0210R2 - Hydraulic Power - Plate Assembly Attachment Points

#### **Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters**

CF-2016-39 - Main Rotor - Pitch Link Bearing Wear

#### **Bell Helicopter Textron UH-1 (All Variants) Series Helicopters**

2016-23-09 - Main Rotor Blade Cracking - Inspection

#### **Sikorsky Aircraft Corporation S-76 Series Helicopters**

2016-23-10 - Autopilot - Rotorcraft Flight Manual Revision

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

AD/A320/21 Amdt 2 - Main Landing Gear Wheel Axle

2016-0238 - Fuselage - Door Stop Fitting Holes at Frames 66/68 - Inspection / Repair

2016-0239 - Time Limits / Maintenance Checks - Airworthiness Limitation Section Part 2

#### **Beechcraft 300 Series Aeroplanes**

AD/BEECH 300/8 Amdt 3 - Wing Attach Fittings, Bolts and Nuts

#### **Boeing 727 Series Aeroplanes**

2016-19-16 - Doors - Main Cargo Door - Cam Latch and Latch Pin Inspection and Modification

#### **Boeing 737 Series Aeroplanes**

2016-23-08 - Fuselage - Frames and Bulkheads - Body Stations 559, 578 and 601 - Body Frame and Overwing Stub Beam Inspection and Repair

#### **Boeing 747 Series Aeroplanes**

2016-24-02 - Flap Track - Transmission Aft Bearing Plate Assemblies - Replacement

### **Boeing 777 Series Aeroplanes**

2016-23-02 - Nacelles/Pylons - Aft Fairing - Aft Fairing Lower Spar Web and Support Structure - Inspection

### **Boeing 787 Series Aeroplanes**

2016-24-09 - Flight Controls - Primary Flight Control Function - Flight Control Module Reset

### **Bombardier CL-600 Series Aeroplanes**

CF-2016-37 - Fuselage - Special Detailed Inspection of the Upper Latch Pins of the Forward Passenger Door

CF-2016-38 - Auto Flight - Rudder Controls - Yaw Damper Uncommanded Movement

### **Bombardier DHC-8 Series Aeroplanes**

CF-2009-29R2 - Nose Landing Gear - Loss of Pivot Pin Retention Bolt

### **Saab 340 Series Aeroplanes**

2016-0234 - Lights - Passenger Reading Light / Circuit Breaker - Replacement

### **Turbine Engines**

#### **Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series**

2016-0235 - Engine - Front Support - Replacement

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arrius Series

2016-0003R1 - Engine Fuel & Control - Main Injector Half-Manifolds and Preference Injector - Replacement