



## CASA AD Biweekly 13/2016 – 23 June 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 10 June and 23 June 2016.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2016-0104-E (Correction 2) - Flight Prohibition

#### **Airbus Helicopters (Eurocopter) AS 355 Series Helicopters**

2016-0109 - Fuel - FUELTRON Flowmeter - Removal

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2016-0118-E - Main Rotor - Main Rotor Blade Erosion Protection Shell - Inspection / Replacement

#### **Airbus Helicopters (Eurocopter) EC 225 Series Helicopters**

2016-0104-E (Correction 2) - Flight Prohibition

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

2016-0115-E - Rotor(s) - Main Rotor Mast / Starflex Star / Mast Connecting Bolts - Replacement

#### **Bell Helicopter Textron Canada (BHTC) and Agusta Bell 206 Series Helicopters**

2016-0117 - Main Rotor Drive - Freewheel Lubrication System - Inspection / Cleaning / Modification

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2016-0113 - Flight Controls - Flap Interconnecting Strut - Identification / Modification / Replacement

2016-0114 - Fuel - Fuel Vent Protector - Inspection / Replacement

2016-0122 - Auto Flight - Flight Management and Guidance Computer - Replacement

#### **Boeing 777 Series Aeroplanes**

2016-11-16 - Engine Exhaust

#### **Bombardier CL-600 Series Aeroplanes**

CF-2016-17R1 - Wings - Life Limit Introduction for Side Brace Fitting Shaft Installed on Main Landing Gear (MLG)

CF-2016-20 - Equipment/Furnishings - Electrical Short of Bonding Jumper causing Burnt Water Supply Line and Smoke in Cabin

CF-2016-19R1 - Cold Weather Operations - Introduction of Low Temperature Ground Wing Anti-Ice System

#### **Dassault Aviation Falcon 7X Series Aeroplanes**

2016-0116 - Fuselage - Frame 36/39 Bore Holes and Bolts - Inspection / Replacement

## **Dassault Aviation Falcon 50 and 900 Series Aeroplanes**

2016-0110 - Equipment / Furnishings - Cockpit Seat / Locking Springs - Replacement

## **Dassault Aviation Falcon 2000 Series Aeroplanes**

2016-0110 - Equipment / Furnishings - Cockpit Seat / Locking Springs - Replacement

## **Fokker Services F28 Series Aeroplanes**

2016-0125 - Time Limits / Maintenance Checks - ALS Part 2 - Airworthiness Limitations Items and Safe Life Items - Implementation

## **Fokker Services F100 (F28 Mk 100) Series Aeroplanes**

2016-0125 - Time Limits / Maintenance Checks - ALS Part 2 - Airworthiness Limitations Items and Safe Life Items - Implementation

## **Turbine Engines**

### **Rolls Royce Turbine Engines - RB211 TRENT 700 Series**

2016-0120 - Engine Fuel & Control - Low Pressure Fuel Tubes and Clips / Fuel Oil Heat Exchanger Mounts - Inspection / Replacement / Modification

## **Equipment**

### **Oxygen Systems**

2016-11-20 - B/E Aerospace Protective Breathing Equipment (PBE) P/N 119003-11 - Inspection / Replacement