



CASA AD Biweekly 26/2021 – 24 December 2021

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 17 December and 31 December 2021.

Note: No ADs will be published 25 December 2021 through 3 January 2022 inclusive due to the CASA shutdown.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2021-0282 - Tail Rotor - Tail Rotor Head Pitch Change Unit Bearing Spacer - Marking / Check

2021-0283-E - Fuselage - Rear Transmission Bearing Support - Inspection

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2021-0282 - Tail Rotor - Tail Rotor Head Pitch Change Unit Bearing Spacer - Marking / Check

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

2021-0287 - Equipment / Furnishings - Seat Belt Restraint System - Inspection

2021-0289-E - Rotorcraft Flight Manual / Section 2 and 3 - Amendment

2021-0290 (Correction) - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Brantly International B-2 Series Helicopters

2021-26-09 - Tail Rotor Hub - Inspection / Replacement

Leonardo Helicopters (AgustaWestland) A109 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2015-0226R6 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Below 5700 kgs

Piper PA-23 (Apache and Aztec) Series Aeroplanes

AD/PA-23/70 Amdt 2 - Stabilator Tip Tube and Weight Assembly - Inspection and Modification - CANCELLED
2021-25-11 - Horizontal Stabiliser Structure

Above 5700 kgs

Airbus A330 Series Aeroplanes

2021-0281 - Aircraft Flight Manual / Engine Bleed Air System - Amendment; and Pneumatic - Engine Bleed Air System - Maintenance Tasks
2021-0286 - Placards and Markings - Safety Placards for First Centre Row Passenger Seats - Installation

Airbus A380 Series Aeroplanes

2021-0280 - Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection
2021-0284 - Engine Fuel & Control - Electronic Engine Control Software - Update
2021-0285 - Flight Controls - Aileron Servo Controls - Replacement

BAe Systems (Operations) BAe 146 and AVRO 146-RJ Series Aeroplanes

AD/BAe 146/71 Amdt 3 - NLG Retraction Jack Attachment Boss - CANCELLED
G-2021-0016 - Fuselage - Left Hand Nose Landing Gear Well Sidewall & Retraction Jack Attachment - Inspection

BAe Systems (Operations) Jetstream 3100 and 3200 Series Aeroplanes

G-2021-0017 - Flight Controls - Rudder and Elevator Flight Control Cable Terminals - Inspection

Boeing 777 Series Aeroplanes

2021-19-15 - Galley Attendant Seat Fitting Installations

Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes

CF-2021-49 - Landing Gear - Landing Gear System - General

Turbine Engines

General Electric Turbine Engines - CF34 Series

2021-26-19 - High Pressure Turbine Rotor Stage 1 Disk