

# CASA AD Biweekly 5/2023 – 9 March 2023

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 23 February 2023 and 9 March 2023.

## Rotorcraft

## Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2021-0012R1 - Windows - Jettisoning System - Modification 2023-0049 - Fuselage - Main Gearbox Suspension Bar Attachment Plates - Inspection / Measurement

## Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2023-0044 - Main Rotor Drive - Main Gearbox Planet Gear - Inspection

## Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2023-0044 - Main Rotor Drive - Main Gearbox Planet Gear - Inspection

## Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2023-0042 - Main Rotor - Rotating Swashplate Yokes - Inspection / Rework / Service Life Limit 2021-0012R1 - Windows - Jettisoning System - Modification

## Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

CF-2023-11 - Fuel System - Standpipe Assembly Sharp Edges Leading to Fuel Quantity Wiring Harness Chafing Condition

## Bell Helicopter Textron Canada (BHTC) 505 Series Helicopters

CF-2023-16 - Engine - Fuel and Control - Change of Flight Manual Limitations

## Below 5700 kgs

#### **Cirrus Design SF50 Series Aeroplanes**

2023-04-20 - Uncommanded Activation of the Cirrus Airframe Parachute System

## **CEAPR and Alpha Aviation (Avions Pierre Robin) Robin Series Aeroplanes**

2023-0048-E - Wings - Main Wing Spar

## Above 5700 kgs

#### Airbus A319, A320 and A321 Series Aeroplanes

2022-0165R1 - Aircraft Flight Manual - Section Abnormal Procedures - Amendment

#### **Airbus A380 Series Aeroplanes**

2023-0043 - Fire Protection - Fire Extinguishers - Pressure Check

#### **Boeing 777 Series Aeroplanes**

2023-03-04 - Fuel System - Inspection

#### **Bombardier BD-700 Series Aeroplanes**

CF-2023-17 - Pneumatic - Non-Conforming Bleed Air Leak Detection System Sensing Elements

#### **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2023-14 - Landing Gear - Nose Wheel Steering System - Electronic Control Module Filter Plate Connector Failure

#### Dassault Aviation Mystere-Falcon 50 and 900 and Falcon 900EX Series Aeroplanes

2023-0046 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment 2023-0047 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

#### **Embraer ERJ 190 Series Aeroplanes**

2023-02-02 - Main Landing Gear Side Stay Upper Spindle Assembly

#### Embraer EMB-135 and EMB-145 Series Aeroplanes

2023-03-01 - Missing Sealant Between Rib 3 and Wing Skin

## Piston Engines

## **Continental Aerospace Technologies (Continental Motors) Piston Engines**

2023-04-08 - Counterweight Retaining Rings