



Australian Government  
Civil Aviation Safety Authority

## CASA AD Biweekly 2/2020 – 23 January 2020

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 10 January and 23 January 2020.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) EC 175 Series Helicopters**

2020-0004 - Fuselage - Lower Fuselage Fuel Tank Structure and Equipment Electrical Connectors - Rework / Relocation

### **Below 5700 kgs**

#### **Diamond Aircraft Industries DA 42 and DA 62 Series Aeroplanes**

2020-0008 - Flight Controls - Flap Control System / Bellcrank Assembly - Inspection / Modification

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2020-0005 - Fuselage - Windshield Central Lower Node Continuity Fittings - Inspection / Modification

#### **Boeing 737 Series Aeroplanes**

2019-23-14 (Correction) - Fuel Tank Ignition Prevention and Nitrogen Generation System - New / Revised Airworthiness Limitations  
2020-01-11 - Air Conditioning - Left Temperature Control Valve and Control Cabin Trim Air Modulating Valve

#### **De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes**

CF-2020-01 - Fuel System - Non-Conforming Installation of Electrical Bonding Jumpers

#### **Embraer EMB-505 (Phenom 300) Series Aeroplanes**

2020-01-01 - Attaching Bolts of Balance Mass Weights to Elevators - Replacement

### **Turbine Engines**

#### **CFM International Turbine Engines - CFM56 Series**

2020-0007 - Engine - Rotating Air High Pressure Turbine Front Seal - Replacement

#### **General Electric Turbine Engines - GE90 Series**

2020-01-55 - High Pressure Turbine Interstage Seal Part Number 2505M72P01 or 2448M33P01 - Removal From Service

#### **Rolls Royce Turbine Engines - RB211 TRENT 900 Series**

2020-0003 - Engine Fuel & Control - Hydro-mechanical Metering Units - Removal from Service