



Australian Government  
Civil Aviation Safety Authority

## CASA AD Biweekly 6/2022 – 24 March 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 11 March and 24 March 2022.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

2022-0051 - Fuselage - Rear Structure Junction Frame Reinforcement Angles - Inspection

2022-0053 - Landing Gear - Skid-Type Landing Gear - Inspection

#### **Airbus Helicopters (Eurocopter) AS 355 Series Helicopters**

2022-0051 - Fuselage - Rear Structure Junction Frame Reinforcement Angles - Inspection

#### **Airbus Helicopters (Eurocopter) EC 120 Series Helicopters**

2022-0053 - Landing Gear - Skid-Type Landing Gear - Inspection

#### **Bell Helicopter Textron 204 Series Helicopters**

2022-06-03 - Main Rotor Strap Pin

#### **Bell Helicopter Textron 205 Series Helicopters**

2022-06-03 - Main Rotor Strap Pin

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies

#### **Bell Helicopter Textron 212 Series Helicopters**

2022-06-03 - Main Rotor Strap Pin

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies

#### **Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters**

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies (Mandatory for Bell Helicopter Textron 412 only)

2022-0046 - Fuselage - Tailboom Attachment - Inspection / Replacement

2022-07-03 - Collective Lever Fatigue Life

#### **Bell Helicopter Textron UH-1 (All Variants) Series Helicopters**

2022-06-05 - Main Rotor Strap Pin

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies

#### **Leonardo Helicopters (AgustaWestland) A109 Series Helicopters**

2022-0037\_Correction - Main Rotor System - Main Rotor Rotating Scissor Assembly - Inspection

#### **Leonardo Helicopters (AgustaWestland) A119 Series Helicopters**

2022-0037\_Correction - Main Rotor System - Main Rotor Rotating Scissor Assembly - Inspection

#### **Sikorsky Aircraft Corporation S-76 Series Helicopters**

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies

## **Sikorsky Aircraft Corporation S-92 Series Helicopters**

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies

## **Below 5700 kgs**

### **CEAPR and Alpha Aviation (Avions Pierre Robin) Robin Series Aeroplanes**

2022-0041 - Flight Controls - Flight Controls Cables - Inspection

## **Above 5700 kgs**

### **Airbus A330 Series Aeroplanes**

2021-0252 - Time Limits / Maintenance Checks - Fuel Airworthiness Limitations - ALS Part 5 - Amendment

2022-0049 - Landing Gear - Nose and Main Landing Gear Main Fittings and Main Landing Gear Sliding Pistons - Replacement

### **Boeing 747 Series Aeroplanes**

2022-06-16 - Airplane Systems - 5G C-Band Wireless Broadband Interference - Aircraft Flight Manual Revision

### **Boeing 777 Series Aeroplanes**

2022-06-10 - Pratt & Whitney 4000 Series Thrust Reverser Debris Shields

2022-06-11 - Pratt & Whitney PW4000 Engine Inlet Modification

### **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2022-10 - Equipment/Furnishings - Cockpit Smoke Hood

### **De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes**

CF-2022-12 - Landing Gear - Lubrication of Main Landing Gear

### **Deutsche Aircraft Dornier 328 Series Aeroplanes**

2022-0050 - Placards - Installation; and Emergency Equipment - Gloves - Installation; and Aircraft Flight Manual - Emergency Procedure - SMOKE - Amendment

## **Turbine Engines**

### **Rolls Royce Deutschland Turbine Engines - RB211 TRENT 700 Series**

2022-0055 - Engine - Intermediate Pressure Compressor Rotor Shaft - Inspection

## **Equipment**

### **Supplementary Equipment (including Rescue Hoists)**

2022-05-10 - Goodrich Externally-Mounted Hoist Assemblies (Mandatory for FAA (US) Rotorcraft only. Refer individual Rotorcraft AD series')