



CASA AD Biweekly 14/2021 – 15 July 2021

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 2 July and 15 July 2021.

Rotorcraft

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2019-0305R1 - Wiring Harness - Cabin Wiring Harness - Inspection

2021-0160 - Main Rotor System - Flex Control Unit Bearing Pin - Inspection / Modification

Bell Helicopter Textron 204 Series Helicopters

2021-15-51 - Outboard Main Rotor Hub Strap Pin

Bell Helicopter Textron 205 Series Helicopters

2021-15-51 - Outboard Main Rotor Hub Strap Pin

Bell Helicopter Textron 212 Series Helicopters

2021-15-51 - Outboard Main Rotor Hub Strap Pin

Bell Helicopter Textron UH-1 (All Variants) Series Helicopters

2021-15-52 - Outboard Main Rotor Hub Strap Pin

Helicopteres Guimbal Cabri G2 Series Helicopters

2021-0155 - Helicopteres Guimbal - Cabri G2 - Rotors Flight Control - Main Rotor Scissors Fittings - Inspection / Replacement

Below 5700 kgs

Lancair Series Aeroplanes

AD/LANCAIR/1 Amdt 2 - Canopy Latching

True Flight Holdings (Gulfstream / Grumman / American General) AA-1 Series Aeroplanes

2021-14-12 - Inspection of Horizontal Stabilisers

True Flight Holdings (Gulfstream / Grumman / American General) AA-5 Series Aeroplanes

2021-14-12 - Inspection of Horizontal Stabilisers

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2021-0115R1 - Fuel - Pumps - Replacement

2021-0166 - Equipment / Furnishings - Passenger Seats - Inspection

Airbus A380 Series Aeroplanes

2021-0153 - Airbus A380 - Fuselage - Rear Fuselage Lateral / Lower Frame Joint - Inspection

2021-0162 - Equipment / Furnishings - Doghouse Placard - Installation

Turbine Engines

GE Aviation Czech (Walter) Turbine Engines - M601, H75, H80 and H85 Series

2021-0154 - Engine - Propeller Shaft - Replacement [Life Limit]

International Aero Engines AG (IAE) Turbine Engines - V2500 series

2021-11-51 - High-Pressure Turbine 1st and 2nd Stage Disks - Inspection / Replacement