



CASA AD Biweekly 19/2024 – 19 September 2024

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 6 September and 19 September 2024.

Rotorcraft

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2024-0177 - Time Limits / Maintenance Checks - Airworthiness Limitations Section / 04-10 Limitations and 04-20 Inspections - Amendment

Below 5700 kgs

Textron Aviation (Cessna) 525 Series Aeroplanes

2024-15-09 - Tamarack Active Technology Load Alleviation System (STC SA03842NY) - Placard Installation / AFM Revision

Above 5700 kgs

Airbus A380 Series Aeroplanes

2024-0101R1 - Fuel - Engine Low Pressure Shut Off Valve Electrical Harness Routing - Modification

Airbus Canada BD-500 Series Aeroplanes

CF-2024-32 - Electrical System Installation - Frame (FR) 51 Bulkhead Connectors - Inadequate Electrical Bonding

Boeing 747 Series Aeroplanes

2024-16-03 - Fuel Tank Fastener Collar Cap Seals

Boeing 767 Series Aeroplanes

2024-15-05 - Main Equipment Centre Electrical Support Bracket - Installation

Boeing 777 Series Aeroplanes

2024-15-03 - Captain's and First Officer's Seats

2024-15-07 - Nitrogen Enriched Air Distribution System Cover Plate Assembly Electrical Bonding - Installation

Boeing 787 Series Aeroplanes

2024-16-07 - Thrust Management and Displays and Crew Alerting Operational Program Software Update

Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes

CF-2024-31 - Flight Controls - Flap System On-Board Recorder (FSOBR) effects on Flap Control Unit

Fokker Services F28 Series Aeroplanes

2024-0176 - Landing Gear - Main Landing Gear Piston - Inspection

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2024-0176 - Landing Gear - Main Landing Gear Piston - Inspection

Turbine Engines

CFM International Turbine Engines - LEAP-1A and LEAP-1C Series

2024-0175 - Engine - Fuel Nozzle - Replacement

Pratt and Whitney Canada Turbine Engines - PT6A Series

CF-2024-33 - Engine - First-Stage Power Turbine (PT1) Blade Failure