



## CASA AD Biweekly 2/2022 – 27 January 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 14 January and 27 January 2022.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2022-0012 - Time Limits / Maintenance Checks - Airworthiness Limitations / Mechanical Part Torque Cycles - Re-calculation / Replacement  
2022-0016-E - Equipment / Furnishings - Hoist Attachment Fittings - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2021-0287 (Correction) - Equipment / Furnishings - Seat Belt Restraint System - Inspection

#### **Bell Helicopter Textron UH-1 (All Variants) Series Helicopters**

2021-26-16 - KAflex Main Driveshaft - Life Limit

#### **Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters**

2022-0010 - Navigation - Glide Slope Antenna - Inspection / Cleaning / Replacement

#### **Sikorsky Aircraft Corporation S-92 Series Helicopters**

2022-02-01 - Main Rotor Stationary Swashplate Assembly - Inspection / Replacement

### **Below 5700 kgs**

#### **Piper PA-32 (Cherokee Six) Series Aeroplanes**

AD/PA-32/42 Amdt 3 - Wing Structural Fatigue Life Limitation

### **Above 5700 kgs**

#### **Boeing 737 Series Aeroplanes**

2021-25-05 - Fuselage Crown Skin Panels  
2021-26-03 - Fuselage Frame Splices between Stringer S-13 and S-14 Station (STA) 360 to STA 520 and STA 727A to STA 907

#### **Boeing 747 Series Aeroplanes**

2021-26-10 - Boeing Material Specification 8-39 Urethane Foam System Tube/Wire Seals - Replacement

#### **Boeing 787 Series Aeroplanes**

2022-02-16 - Airplane Flight Manual (AFM) - Limitations and Operating Procedures Sections Revision

## **Gulfstream Aerospace (Israel Aircraft Industries) G150 Series Aeroplanes**

ISR-I-57-2021-12-3 - Wings-Flaps-Fairing Seal Repair

## **Gulfstream Aerospace G-1159, G-IV and GV Series Aeroplanes**

2022-02-15 - Nose Wheel Steering Servo Valve Manifold

## **Turbine Engines**

### **GE Aviation Czech (Walter) Turbine Engines - M601, H75, H80 and H85 Series**

2022-0008 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

### **General Electric Turbine Engines - CF6 Series**

2022-02-18 - Left-Hand Rear Mount Link Assembly - Reduced Life Limit