



CASA AD Biweekly 20/2019 – 3 October 2019

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 20 September and 3 October 2019.

Lighter Than Air

Hot Air Balloons

2019-0245 - Burner - Modification

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

AD/ECUREUIL/82 - Electric Hoists - CANCELLED

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

AD/AS 355/70 - Electric Hoists - CANCELLED

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2012-0108R1 - Fuselage - Frame No.9 - Inspection / Repair

Bell Helicopter Textron Canada (BHTC) 206 and Leonardo Helicopters (Agusta) AB206 Series Helicopters

CF-2019-34 - Tail Rotor Drive - Failure of Tail Rotor Drive Shaft Coupling Bolted Connections

Bell Helicopter Textron Canada (BHTC) 505 Series Helicopters

CF-2019-35 - Fuselage Structure - Fretting or Cracking of Airframe Truss Clevis Lower Lug

Bell Helicopter Textron UH-1 (All Variants) Series Helicopters

AD/UH-1/20 - Tail Boom and Fin - Fretting and Cracking

Below 5700 kgs

CEAPR and Alpha Aviation (Avions Pierre Robin) Robin Series Aeroplanes

2019-0242 - Aircraft Flight Manual - Use of the Disc Braking System - Amendment

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2019-0233 (Correction) - Wings - Overwing Panel - Inspection

Airbus A330 Series Aeroplanes

2019-0219 (Correction) - Fuselage - Fuselage Bulk Cargo Door Frames - Inspection / Repair

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2019-0236 - Landing Gear - Main Landing Gear Bush - Inspection

De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes

CF-2017-05R2 - Fuel System - Motive Flow Line Fouling and Motive Flow Line and Pressure Relief Line Broken P-Clamps

Pilatus Aircraft PC-24 Series Aeroplanes

2019-0240 - Fuel - Saddle Clamps / Motive-Flow Fuel Pipes - Replacement / Alignment

Turbine Engines

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2019-0230 (Correction) - Engine - Oil Service Pipe Sealing Rings - Inspection / Replacement / Modification / Rework

Equipment

Airconditioning Equipment

AD/AIRCON/12 Amdt 5 - Hartzell Engine Technologies, Kelly Aerospace Power Systems, and Janaero Devices - Cabin Combustion Heaters

Radio Communication (including Emergency Transmitters and Navigation Equipment)

2019-0235 (Correction) - Equipment / Furnishings - Emergency Locator Transmitter - Inspection / Modification / Replacement