



CASA AD Biweekly 14/2013 – 11 July 2013

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 28 June 2013 and 11 July 2013.

Rotorcraft

Bell UH-1 Series Helicopters

2013-13-14 - Main Rotor Hub Inboard Strap Fittings

Eurocopter AS 332 (Super Puma) Series Helicopters

2013-0138-E - Main Rotor Drive - Main Gear Box Bevel Gear Vertical Shaft - Inspection / Modification / Replacement / Limitation

Eurocopter AS 350 (Ecureuil) and EC 130 Series Helicopters

AD/ECUREUIL/10 Amdt 6 - Retirement Life - Fatigue Critical Components - CANCELLED
2013-0133 - Tail Rotor - Tail Rotor Hub Pitch Horn - Inspection / Replacement

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

2013-0133 - Tail Rotor - Tail Rotor Hub Pitch Horn - Inspection / Replacement

Eurocopter BK 117 Series Helicopters

2013-0135 - Time Limits and Maintenance Checks - Airworthiness Limitation Items - Amendment

Eurocopter EC 225 Series Helicopters

2013-0138-E - Main Rotor Drive - Main Gear Box Bevel Gear Vertical Shaft - Inspection / Modification / Replacement / Limitation

Below 5700 kgs

Cessna 170, 172, F172, FR172 and 175 Series Aeroplanes

AD/CESSNA 170/67 - Oil Pressure Switch - CANCELLED
2013-11-11 - Oil Pressure Switch

Cessna 180, 182 and Wren 460 Series Aeroplanes

AD/CESSNA 180/80 - Oil Pressure Switch - CANCELLED
2013-11-11 - Oil Pressure Switch

Cessna 206 Series Aeroplanes

AD/CESSNA 206/51 - Oil Pressure Switch - CANCELLED
2013-11-11 - Oil Pressure Switch

Piper PA-46 (Malibu) Series Aeroplanes

2013-13-01 - Fuel - Fuel Vent Valve - Inspection

TECNAM P2006T Series Aeroplanes

2013-0134 - Landing Gear - Nose Landing Gear Lower Link - Inspection / Replacement

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

AD/A320/58 Amdt 2 - Centre Fuselage, Pick-up Angle Between Frame 35 and 36 - CANCELLED

2011-0137R1 - Equipment / Furnishings - Passenger Compartment Class Divider / Gas Spring Damper - Inspection / Replacement

2013-0137 - Fuselage - Center Fuselage Transition and Pick Up Angle - Inspection / Modification

Boeing 747 Series Aeroplanes

2013-13-05 - Fuselage Skin - Inspection

2013-13-11 - Fuel - Engine Fuel Feed System - Engine Fuel Suction Feed Operational Test

Boeing 767 Series Aeroplanes

AD/B767/178 Amdt 1 - Auto-Speedbrake Control System

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

AD/CL-600/36 Amdt 1 - Elevator Flutter Damper Shear Pins

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2007-32R2 - Fuel System Safety - Introduction of Maintenance Tasks

CF-2013-17R1 - Fractured Wing-to-Fuselage Strut Attachment Joint Bolt

Learjet 60 Series Aeroplanes

2013-13-09 - Landing Gear

Turbine Engines

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2012-0260R1 - Engine Oil System - Fuel-to-Oil Heat Exchanger - Replacement [Time Between Overhaul]

Equipment

Supplementary Equipment

2013-06-51 - Equipment / Furnishing - Hoist - Inspection / Replacement