



CASA AD Biweekly 22/2014 – 30 October 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 17 October 2014 and 30 October 2014.

Rotorcraft

AgustaWestland A109 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

AgustaWestland AB139 and AW139 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2014-0229-E - Oil - Main Gearbox Oil Cooler Hopper - Inspection

2014-0233 - Rotor Drive - Hydraulic Pump Bearing - Inspection / Replacement

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2014-0180R1 - Main Rotor - Swashplate Assembly - Inspection / Replacement

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters

2014-0180R1 - Main Rotor - Swashplate Assembly - Inspection / Replacement

2014-0230 - Main Rotor Drive - Main Gearbox - Inspection

2014-0235 - Equipment / Furnishings - Rescue Hoist Control Grip - Inspection / Replacement

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement

2014-0236 - Lights - Emergency Lighting Rotorcraft Flight Manual Amendment / Operational Procedure

Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters

2014-0201 - Equipment / Furnishing - Hoist - Test / Replacement (Mandatory for AgustaWestland AB 412 only)

Kawasaki BK 117 Series Helicopters

TCD-8518-2014 - Hoist Control Pendant Wiring Harness
TCD-8201A-2014 - Goodrich Rescue Hoist

Below 5700 kgs

Viking Air DHC-2 (Beaver) Series Aeroplanes

CF-2014-38 - Flight Controls - Failed Locknuts (MS21042) in the Horizontal Stabilizer

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2014-0234 (Correction) - Fuel - Fuel Vent Protector - Inspection / Replacement

Airbus A330 Series Aeroplanes

2014-0228 - Doors - Forward Cargo Door Beam 3 Area - Inspection

Beechcraft 400 Series Aeroplanes

2014-21-06 - Pitch Trim Actuator

Bombardier CL-600 Series Aeroplanes

CF-2014-36 - Oxygen - Oxygen System Flexible Hose - Incorrect Burst Pressure
CF-2014-37 - Oxygen - Oxygen System Flexible Hose - Incorrect Burst Pressure

Bombardier DHC-8 Series Aeroplanes

CF-2014-31R1 - Electrical Power - Generator Undervoltage

Dassault Aviation Falcon 7X Series Aeroplanes

2013-0128R1 (Correction) - Landing Gear - Nose Wheel Steering - Airplane Flight Manual Change

Piston Engines

Technify Motors (Thielert) Piston Engines

2014-0232 - Engine - Clutch Assembly - Identification / Replacement

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PT6A Series

2011-25-12 - Failure of First Stage Reduction Sun Gears