



CASA AD Biweekly 5/2014 – 6 March 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 21 February 2014 and 6 March 2014.

Rotorcraft

Agusta AB139 and AW139 Series Helicopters

2012-0076R2 - Tail Rotor - Tail Rotor Blades - Inspection / Replacement
2014-0048 - Fuselage - Subfloor STA 2105 Inspection/Modification

Eurocopter BK 117 Series Helicopters

2014-0046-E - Optional Equipment - External Rescue Hoist System - Deactivation

MD Helicopters MD900 Series Helicopters

97-12-02 - Collective Drive Link Assembly
97-20-12 - Main Rotor Swashplate Bearing
98-12-30 - Main Rotor Hub Assembly
99-05-08 - Main Rotor Drive Shaft, Pitch Plate Assembly and Spherical/Slider Main Rotor Bearing
2000-10-06 - Drive Shaft Assembly
2000-18-08 - Non-rotating Swashplate Assembly
2001-25-51 - Integrated Instrument Display System (IIDS)
2002-10-05 - Main Rotor Upper Hub
2002-15-07 - Lateral Mixer Bellcrank Assembly
2002-22-51 - Main Rotor Support Static Mast
2002-23-03 - Longitudinal Drive Link
2003-14-51 - Main Rotor Blade Retention Bolt
2004-16-08 - Fan Input Force Limiting Control Rod
2006-18-01 - Notar Fan System Tension-torsion (TT) Straps
2008-08-11 - Control Pedal Cracking
2008-17-51 - Forward Directional Control Cable
2009-07-13 - Gross Weight Limit
2010-06-06 - Life Limits for Various Parts
2011-22-08 - Vertical Stabilizer Control System (VSCS) Tube Adapter
2012-21-01 - Main Rotor Lower Hub Assembly
2013-03-03 - Fan Blade Tension-Torsion Strap (T-T strap) - Inspection / Replacement
2013-20-16 - Main Rotor Blade Retention Bolts

Kawasaki BK 117 Series Helicopters

TCD-8379-2014 - Rescue Winch Hook Damper

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

2014-0045 (Correction) - Oxygen - Passenger Gaseous Oxygen System - Modification

Airbus Industrie A330 Series Aeroplanes

2010-0081R1 - Flight Controls - Elevator Servo Controls
2013-0267R1 - Landing Gear - Main Landing Gear Bogie Beam - Inspection / Repair / Modification
2014-0050 - Auto flight - Auto Pilot / Flight Director TCAS function - De-Activation

Airbus Industrie A380 Series Aeroplanes

2014-0041 - Electric and Electronic Common Installation - Left Hand Pylons / Clearance between G Route and Door Restrainer - Inspection / Modification

BAe Systems (Operations) Jetstream 4100 Series Aeroplanes

2014-0043 - Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment / Implementation

Boeing 727 Series Aeroplanes

2014-03-21 - Main Wheel Well Pressure Floor - Inspection

Boeing 737 Series Aeroplanes

2014-03-19 - In-Flight Entertainment (IFE) System Radome Assembly
2014-04-05 - Control Cabin Overhead Wiring
2014-05-02 - Aft Pressure Bulkhead

Boeing 777 Series Aeroplanes

2014-05-05 - Specific Radio Altimeter Transceivers and Antennae - Replacement

British Aerospace BAe 146 Series Aeroplanes

2014-0047 - Fixed Wing Leading Edge and Front Spar Structure

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

2014-0044 - Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment / Implementation

Embraer ERJ-190 Series Aeroplanes

2014-02-01 (Correction) - Replacement of Low-Stage Bleed Check Valves

Fokker F28 Series Aeroplanes

2014-0039 - Fuselage - Tail Section - Inspection / Repair

Fokker F100 (F28 Mk 100) Series Aeroplanes

2014-0039 - Fuselage - Tail Section - Inspection / Repair

Piston Engines

Austro Engine Piston Engines

2013-0213R1 - Engine - Waste Gate Controller - Replacement