



**Australian Government**  
**Civil Aviation Safety Authority**

## CASA AD Biweekly 20/2014 – 2 October 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 19 September 2014 and 2 October 2014.

### **Rotorcraft**

#### **AgustaWestland AB139 and AW139 Series Helicopters**

2014-0215-E - Main Rotor - Rotating Scissors - Inspection / Modification

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2014-0211 - Wiring / Harness - Hoist Control Pendant Wiring Harness - Inspection / Modification

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

2014-0214 - Equipment / Furnishing - External Life Rafts - Inspection

#### **Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters**

2014-0203 - Equipment / Furnishings - External Cargo Hook Installation / Suspension Assembly Nuts - Inspection / Replacement

### **Below 5700 kgs**

#### **Grob-Werke G115 Series Aeroplanes**

2014-0212 - Starting - Starter Solenoid - Inspection

#### **Construzioni Aeronautiche Tecnam P2006T Series Aeroplanes**

2014-0220 - Exhaust - Engine Exhaust Pipe - Inspection / Replacement

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2014-0209 - Fuselage - Centre Fuselage Forward Pressure Bulkhead - Reinforcement

2014-0217 - Auto Flight / Instruments - Stop Rudder Input Warning - Installation / Activation

#### **Airbus A330 Series Aeroplanes**

2014-0219 - Flight Controls - Trimmable Horizontal Stabilizer Actuator - Inspection / Modification

#### **Airbus A380 Series Aeroplanes**

2014-0213 - Fuselage - Section 19 Upper Cross Fitting Upper Beam Inner Cap Joints - Inspection

#### **Boeing 747 Series Aeroplanes**

2014-19-03 - Migration of Fuse Pins

## **Bombardier CL-600 Series Aeroplanes**

CF-2014-05R1 - Integrated Drive Generator Wire Chafing in Aft Equipment Bay

## **Learjet 35 and 36 Series Aeroplanes**

AD/LEARJET 35/12 - Upper Cabin Door Locking Mechanism - Modification - CANCELLED

## **Saab 340 Series Aeroplanes**

2014-0218 - Flight Controls - Stall Warning and Identification System / Stall Warning Computer - Modification / Replacement

## **Piston Engines**

### **Engines - General**

AD/ENG/6 Amdt 1 - Propeller Strike - CANCELLED

### **Lycoming Piston Engines**

AD/LYC/89 Amdt 4 - Crankshaft Gear

## **Turbine Engines**

### **Engines - General**

AD/ENG/6 Amdt 1 - Propeller Strike - CANCELLED

### **Rolls Royce Deutschland Turbine Engines - BR700 Series**

2012-0161R1 - Engine - Accessory Gearbox Module - Replacement of the Fuel Pump Splined Coupling

### **Rolls Royce Turbine Engines - RB211 Series**

2014-0210 - Engine - Low Pressure Turbine Stage 3 Blades - Replacement (Life Limitation)

## **Equipment**

### **Propellers - Variable Pitch - Hamilton Standard**

AD/PHS/18 Amdt 4 - Hub Cracking

### **Radio Communication (including Emergency Transmitters and Navigation Equipment)**

AD/RAD/93 - Rockwell Collins TDR-94/94D Transponders - Aircraft Type Category - CANCELLED

2010-0003R2 - Navigation - Mode S Transponder Aircraft Type Mode Strapping - Check / Modification