



**Australian Government**  
**Civil Aviation Safety Authority**

## CASA AD Biweekly 23/2015 – 12 November 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 30 October 2015 and 12 November 2015.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2015-0153R1 - Tail Rotor - Rotor Blades - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2015-0220 - Electrical Power - Ground Reference Connection - Inspection / Modification

#### **Sikorsky Aircraft Corporation (Schweizer/Hughes) 269 Series Helicopters**

2015-23-01 - Tail Rotor Driveshaft Splined Fitting - Inspection / Lubrication

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2015-0218 - Fuselage - Cabin / Cargo Compartment Parts - Inspection / Replacement (Wrong Material)

2015-0219 - Fuselage - Cabin / Cargo Compartment Parts - Inspection / Replacement (Improper Heat Treatment)

#### **Airbus A330 Series Aeroplanes**

2015-0212 - Fuselage - Cabin and Cargo Compartments Structural Parts - Inspection

#### **Airbus A380 Series Aeroplanes**

2015-0215R1 - Fuselage - Horizontal Tail Plane Pivot Fittings - Inspection

#### **Boeing 747 Series Aeroplanes**

AD/B747/261 Amdt 2 - Fuselage Station 800 Frame - CANCELLED

#### **Boeing 787 Series Aeroplanes**

2015-22-09 - Lower Lobe Cargo Compartment Stringer Bonded Plugs

### **Piston Engines**

#### **Lycoming Piston Engines**

AD/LYC/90 Amdt 2 - Fuel Injection Supply Lines - CANCELLED