



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 17/2018 – 23 August 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 10 August and 23 August 2018.

Rotorcraft

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2018-0177 - Rotor Drive - Main Gearbox Magnetic Plugs - Inspection

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2018-0176 - Main Rotor Drive - Main Gearbox Magnetic Plug - Replacement

Bell Helicopter Textron Canada (BHTC) and Leonardo Helicopters (Agusta) AB206 Series Helicopters

AD/BELL 206/175 - Engine - Power Turbine Speed Limitations - CANCELLED

2018-0175-E - Engine - Power Turbine Limitations - Operational Limitation

CF-2018-23 - Engine Turbine/Turboshaft - RPM (N2) Steady-State Operation Avoidance Range Limit

Bell Helicopter Textron 212 Series Helicopters

2018-17-01 - Engine Oil Check Valve and Fuel Check Valve - Replacement

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2018-17-01 - Engine Oil Check Valve and Fuel Check Valve - Replacement

Below 5700 kgs

Univair Aircraft (Stinson) 108 Series Aeroplanes

AD/STINSON 108/1 - State of Design Airworthiness Directives

AD/STINSON 108/2 - Stabilizer Leading Edge Attachment - Inspection

Above 5700 kgs

Boeing 787 Series Aeroplanes

2018-17-03 - Cabin Air Compressor Inlet Ice Protection System Lip Heater Wire Bundle

Turbine Engines

Rolls Royce (Allison) Turbine Engines - AE 3007 Series

2018-17-04 - 1st Stage Gas Generator Turbine Wheels or 1st Stage High-Pressure Turbine Wheels - Replacement