



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 25/2018 – 13 December 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 30 November and 13 December 2018.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2018-0260 - Fuselage - Main Gearbox Suspension Bar Fittings and Screws - Life Limit / Replacement
2017-0134R1 - Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter / Oil Cooler - Inspection; and Main Rotor Drive - Epicyclic Module - Replacement / Modification / Reduced Service Life Limit

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2017-0134R1 - Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter / Oil Cooler - Inspection; and Main Rotor Drive - Epicyclic Module - Replacement / Modification / Reduced Service Life Limit

Leonardo Helicopters (AgustaWestland) A119 Series Helicopters

2018-0270 - Leonardo Helicopters (AgustaWestland) A119 Series Helicopters

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2018-0261-E (Correction) - Tail Rotor - Tail Rotor Servo Actuator - Inspection

Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters

2018-0261-E (Correction) - Tail Rotor - Tail Rotor Servo Actuator - Inspection

Below 5700 kgs

Vulcanair (Partenavia) P.68 Series Aeroplanes

2018-0269 - Wings - Center Wing Ribs - Inspection / Modification

Above 5700 kgs

Airbus A380 Series Aeroplanes

2018-0267 - Wings - Movable Flap Track Fairing # 2 U-Frame Bolt-Nut Couples - Inspection

Boeing 737 Series Aeroplanes

2018-23-51 (Correction) - Angle of Attack (AOA) Sensor - Airplane Flight Manual Revision

Boeing 767 Series Aeroplanes

AD/B767/73 - Leading Edge Slat Wedge - CANCELLED

Bombardier CL-600 Series Aeroplanes

CF-2018-32 - Auto Flight System - Airplane Flight Manual (AFM) Limitations and Abnormal Procedures
- Velocity Decay during Low Level ALT CAP in One Engine Inoperative Conditions
CF-2018-33 - Avionic System - Airplane Flight Manual Navigation System Limitations - Prohibit Editing
CLIMB TO Altitudes and Use of Temperature Compensation on Flight Management System

Dassault Aviation Falcon 50 and 900 Series Aeroplanes

2018-24-02 - Aileron Reinforcing Straps - FAA STC ST02241SE ST02188SE

Piston Engines

BRP Powertrain (Rotax) Piston Engines

2018-0265-E - Engine - Exhaust Valve - Replacement

Turbine Engines

GE Aviation Czech (Walter) Turbine Engines - M601, H75, H80 and H85 Series

2017-0151R1 - Engine - Exhaust System - Modification

General Electric Turbine Engines - GEnx Series

2018-21-12 - Fuel Manifold

Rolls Royce Deutschland Turbine Engines - BR700 Series

2018-0268 - Engine - Life-Limited Critical Parts - Service Life Calculation / Replacement

Equipment

Electrical Equipment Miscellaneous (including Magnetos)

2018-0259 - Information Systems - Electronic Flight Bag Universal Serial Bus Receptacle - Modification

Seats and Berths

2018-0262 - Equipment / Furnishings - Pilot and Co-pilot Seats - Modification / Inspection

2018-0264 - Equipment / Furnishings - Life Vest Pouch - Inspection