



CASA AD Biweekly 24/2022 - 1 December 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 18 November 2022 and 1 December 2022.

Rotorcraft

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2022-0228 - Airbus Helicopters MBB-BK117 - Rotors Flight Control - Horizontal Control Rods Bolts - Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2022-0231 - Power Plant - Central Firewall Stiffener - Replacement

Bell Helicopter Textron 204 Series Helicopters

2022-20-14 - Main Transmission Housing

Bell Helicopter Textron 205 Series Helicopters

2022-20-14 - Main Transmission Housing

Bell Helicopter Textron 212 Series Helicopters

2022-20-14 - Main Transmission Housing

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2022-20-14 - Main Transmission Housing

Bell Helicopter Textron UH-1 (All Variants) Series Helicopters

2022-20-14 - Main Transmission Housing

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2022-0233-E - Doors - Cockpit Door Handle - Inspection

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2022-0096R1 - Aircraft Flight Manual / Section Limitations - Amendment; and Auto Flight - New Flight Guidance Standard - Modification

2006-0135-CN - CANCELLED: Hydraulic Power - Ram Air Turbine - Speed Limitation

Airbus A330 Series Aeroplanes

2022-0222 - Engine Exhaust - Thrust Reverser Lower Beam - Inspection / Repair

2022-0227 - Pneumatic - High Pressure Valve - Inspection / Replacement

Boeing 747 Series Aeroplanes

2022-23-12 - High Temperature Composite Trim Air Diffuser Ducts

Boeing 777 Series Aeroplanes

2022-23-10 - Potable Water System - Shroud Installation

2022-23-11 - Fuel Quantity Indicating System

Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes

CF-2022-66 - Fire Protection - Inspection and Replacement of Defective Cargo Fire Extinguisher Containers

De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes

CF-2022-63 - Fuselage - Wing-to-Fuselage Joint - Moisture Ingress Between Front and Rear Spar Frame Segments

Turbine Engines

Rolls Royce Deutschland Turbine Engines - RB211 Series

2022-0232 - Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment

Safran Helicopter Engines (Turbomeca) Turbine Engines - Makila Series

2022-0223 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

2022-0224 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment