



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 6/2023 – 23 March 2023

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 10 March 2023 and 23 March 2023.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2023-0064 - Main Rotor - Pitch Rod Upper Links - Marking / Inspection

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2023-0064 - Main Rotor - Pitch Rod Upper Links - Marking / Inspection

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2023-0064 - Main Rotor - Pitch Rod Upper Links - Marking / Inspection

Above 5700 kgs

Airbus A330 Series Aeroplanes

2023-0052 - Fuel - Inner Fuel Tanks - Leak Test

2023-0053 - Fuselage - Rear Fuselage - Modification

2023-0054 - Fuselage - Rear Fuselage - Modification

2023-0056 - Airborne Auxiliary Power - Auxiliary Power Unit Scroll Housing Assembly - Replacement

2023-0057 - Airborne Auxiliary Power - Auxiliary Power Unit Fuel Control Unit - Replacement

Boeing 747 Series Aeroplanes

2023-03-15 - Inspection of Trim Air Diffuser Ducts

Bombardier BD-700 Series Aeroplanes

CF-2023-18 - Pneumatic - Non-Conforming Bleed Air Leak Detection System Sensing Elements

Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes

CF-2023-19 - Pneumatic - 14th Stage Bleed Duct Missing Insulation

Dassault Aviation Falcon 7X Series Aeroplanes

2023-0063 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Deutsche Aircraft Dornier 328 Series Aeroplanes

2023-0065 - Flight Controls - Rudder Control Rod - Functional Check / Inspection

Embraer EMB-505 (Phenom 300) Series Aeroplanes

2023-02-01R1 - Aileron Servo Clutch Retaining Bolt Corrosion

Piston Engines

Continental Aerospace Technologies (Continental Motors) Piston Engines

2023-05-16 - Counterweight Retaining Rings

Turbine Engines

General Electric Turbine Engines - GE90 Series

2023-04-19 - FPI of Dovetail Pressure Face of HPC Rotor