



CASA AD Biweekly 3/2013 – 7 February 2013

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 25 January 2013 and 7 February 2013.

Rotorcraft

Bell Helicopter Textron 204 Series Helicopters

2012-17-08 - Main Rotor Yoke Cracking - Inspections and Retirement Lives

Bell Helicopter Textron 205 Series Helicopters

2012-17-08 - Main Rotor Yoke Cracking - Inspections and Retirement Lives

Bell Helicopter Textron 212 Series Helicopters

2012-17-08 - Main Rotor Yoke Cracking - Inspections and Retirement Lives

Bell Helicopter Textron 412 Series Helicopters

2013-01-04 - High Aft Crosstube Assemblies - Inspection

Eurocopter BO 105 Series Helicopters

CF-2008-17R2 - Tension-Torsion Straps Failure - CANCELLED

Below 5700 kgs

Piper PA-28 Series Aeroplanes

2013-02-13 - Stabilator Control System - Inspection

Piper PA-32 (Cherokee Six) Series Aeroplanes

2013-02-13 - Stabilator Control System - Inspection

Piper PA-34 (Seneca) Series Aeroplanes

2013-02-13 - Stabilator Control System - Inspection

Piper PA-44 (Seminole) Series Aeroplanes

2013-02-13 - Stabilator Control System - Inspection

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

AD/A320/96 Amdt 2 - Alternate Braking System Check

2011-0160R2 - Equipment / Furnishings - Escape Slide Raft - Modification / Replacement

2013-0022 - Navigation - Angle of Attack Sensor Conic Plates - Replacement

Airbus Industrie A330 Series Aeroplanes

2012-0244R1 - Hydraulic Power - High Pressure Manifold Check Valves - Inspection

2013-0023 - Navigation - Angle Of Attack Probe Conic Plates - Operational Procedure / Replacement

Boeing 737 Series Aeroplanes

2013-02-05 - Cabin Altitude Warning System

2013-02-07 - Equipment / Furnishing - Centre Overhead Stowage (COS) Box - Modification

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2013-03 - Elevator Control System - Erratic Pitch Movement and Oscillatory Behaviour

Piston Engines

Lycoming Piston Engines

AD/LYC/105 Amdt 2 - Oil Filter Converter Plate Gasket

Turbine Engines

CFM International Turbine Engines - CFM56 Series

2013-02-02 - High Pressure Turbine Discs - Forging error, reduced maximum life limits

Equipment

Restraint Equipment

2013-0020 - Equipment & Furnishings - Safety Belts / Torso Restraint Systems - Inspection / Replacement