



CASA AD Biweekly 10/2018 – 17 May 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 4 May and 17 May 2018.

Lighter Than Air

Hot Air Balloons

2018-0107 - Fuel Cell Systems - Lindstrand T30 Propane Cylinders - Removal from Service

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2018-0104 - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection

2014-0114R2 - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection / Repair

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2018-0106 - Rotors Flight Control - Collective Controls / Protective Cover - Modification

Below 5700 kgs

Textron Aviation (Cessna) 400 Series Aeroplanes

2018-03-03R1 - Left and Right Forward Lower Carry Through Spar Caps - Inspection

Above 5700 kgs

ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes

2018-0105 - Electric / Electronic Common Installation - Electrical Harness Brackets and Wire Bundles - Inspection

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2018-0105 - Electric / Electronic Common Installation - Electrical Harness Brackets and Wire Bundles - Inspection

Boeing 717 Series Aeroplanes

2018-10-08 - Vertical Stabilizer Leading Edge and Front Spar Cap

Boeing 737 Series Aeroplanes

2018-09-08 - Frame Web Common to the Stringer Ties Adjacent to the Air-Conditioning Support Brackets - Inspection

2018-09-13 - Cracking of Forward and Aft Support Fittings for the MLG Beam and Inspar Upper Skin

Boeing 747 Series Aeroplanes

2018-09-12 - Flightcrew Oxygen System Low-pressure Flex-hoses - Replacement

Boeing 787 Series Aeroplanes

2018-10-02 - Standard Attendant Seat Occupant Restraint System - Inspection

Dassault Aviation Falcon 7X Series Aeroplanes

2018-0101 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Gulfstream Aerospace G1159, G-IV and GV Series Aeroplanes

2018-09-04 - Main Landing Gear Actuator Attachment Fitting - Inspection