## Supplemental Type Certificate

Number:

ASA095SY

This certificate issued to:

Dasyl Avionics Pty Ltd 83a Evelvn Street

Macquarie Fields NSW Australia 2564

certifies that the change in the type design for the following product when installed in accordance with the limitations and conditions as specified herein meets the airworthiness requirements of FAR 25.

Original Product:

Type or Type Acceptance Certificate Numbers:

A108 & A222 FAA A16WE

Referenced TC Number (if applicable): Make:

Boeing

Model:

737-200,-300,-400

## Description of Type Design Change:

Installation of ARTEX Model B406-4 Emergency Locator Transmitter in accordance with Dasyl Avionics Pty Ltd Installation and Maintenance Manual No 2021-0001 Rev 3 dated 23rd of July 2015 or later CASA approved revision.

## Limitations and Conditions:

CASA approved Flight Manual Supplements: Doc. No. 2021-0001-12 Rev 2 dated 23<sup>th</sup> July 2015 or later approved revision is required.

Prior to incorporating this design change, the installer shall establish that the relationship between this change and any other modifications incorporated into the aircraft will not adversely affect the airworthiness of the aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data, which is the basis for approval, shall remain in effect until suspended, cancelled or a termination date is otherwise established by the Civil Aviation Safety Authority.

Date of application:

21<sup>st</sup> January 2004

Date reissued:

Date of issuance:

23<sup>rd</sup> February 2004

Date amended: 21st August 2015

This certificate is issued pursuant to Part 21.113A of the Civil Aviation Safety Regulations

Peter Nikolic

Delegate of the Civil Aviation Safety Authority

This certificate may be transferred in accordance with CASR 21.047.