

CASA AD Biweekly 11/2025 – 22 May 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 23 May and 5 June 2025.

Lighter Than Air

Hot Air Balloons

2025-11-10 - Cameron Balloons - Fuel Cylinders - Pressure Relief Valve Adapters - Inspection/Replacement

Rotorcraft

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2024-0228_C1 - Equipment / Furnishings - Hoist - Inspection

Kawasaki BK 117 Series Helicopters

TCD-10467-2025 - Rescue Hoist Assembly - Overload Clutch TCD-10443-2025 - Hoist - Cable Drum Inspection/Replacement

Leonardo Helicopters (AgustaWestland) A109 Series Helicopters

2024-0228_C1 - Equipment / Furnishings - Hoist - Inspection

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2024-0228_C1 - Equipment / Furnishings - Hoist - Inspection

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2025-0120 - Cabin Systems - Antenna Adapter Plate - Inspection 2021-0177R2 - Hydraulic Power - Pylon / Engine Interface Rods - Inspection / Replacement

Airbus A330 Series Aeroplanes

2025-0120 - Cabin Systems - Antenna Adapter Plate - Inspection

Airbus A380 Series Aeroplanes

2025-0120 - Cabin Systems - Antenna Adapter Plate - Inspection 2025-0121 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1, Safe Life Airworthiness Limitations Items - Amendment

BAe Systems (Operations) BAe 146 and AVRO 146-RJ Series Aeroplanes

G-2025-0003 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Amendment

Boeing 757 Series Aeroplanes

2025-11-01 - Body Station Cracking – Inspection

Boeing 787 Series Aeroplanes

2025-06-13 - Floor Beam Side-of-Body Fittings

2025-11-05 - Seat Track Splice Fittings

Dassault Aviation Falcon 7X Series Aeroplanes

2025-0122 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Turbine Engines

General Electric Turbine Engines - CF34 Series

2025-10-04 - HPT Shroud / LPT Nozzle Assemblies - Inspection / Rework

General Electric Turbine Engines - GEnx Series

2025-11-03 - Suspected Iron Inclusion in HPT disks