



Australian Government  
Civil Aviation Safety Authority

## CASA AD Biweekly 20/2025 – 9 October 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 26 September and 9 October 2025.

### **Rotorcraft**

#### **Airbus Helicopters H160 Series**

2023-0139 - Rotorcraft Flight Manual - Amendment  
2024-0063 - Doors - Passenger Jettisonable Window Mechanism - Replacement  
2024-0075 - (STC 10080809) Doors - Passenger Jettisonable Window Mechanism - Replacement  
2024-0223 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment  
2024-0229 - Main Rotor - Swashplate Bearing - Inspections  
2025-0009 - Doors - Jettisonable Window Mechanism - Lubrication / Operational Test  
2025-0040 - Main Rotor - Rotating Scissors Spherical Bearings - Inspection  
2025-0098 - Tail Rotor Drive - Tail Drive Line Rear Shaft and Damper - Inspections  
2025-0051R1 - Equipment / Furnishings - Hoist - Replacement  
2025-0130R1 - Equipment / Furnishings - Emergency Life-Raft System Container Assembly - Replacement  
2025-0162 - Equipment / Furnishings - Emergency Life-Raft Personal Locator Beacon - Inspection  
2025-0161 - Doors - Jettisonable Window System Retaining Rings - Inspection  
2025-0165 - Fuselage - Main Gearbox Mobile Cowlings Rail Supports - Inspection  
2022-0168R1 - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment - Integrated Modular Avionics - Ethernet Network - Inspection  
2025-0218 - Equipment / Furnishings - Emergency Location Transmitter Mounting Tray - Replacement

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2025-0217 - Rotors Flight Control - Fork Lever - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2025-0217 - Rotors Flight Control - Fork Lever - Inspection

#### **Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters**

2025-0213 - Power Plant - Engine Mount Fitting - Inspections / Replacement

### **Below 5700 kgs**

#### **Textron Aviation (Beechcraft) 200 (Super King Air) Series Aeroplanes**

2025-20-11 - Rudder Control Pushrod Failure

### **Above 5700 kgs**

#### **Airbus A330 Series Aeroplanes**

2025-0208 - Flight Controls - Flight Control Primary Computer - Modification  
2025-0216 - Equipment / Furnishings - Doghouse Placard - Replacement  
2025-0219 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1 - Safe Life Airworthiness Limitation Items - Amendment

## **Airbus A380 Series Aeroplanes**

2025-0212 - Wings - Wing Rear Spars - Inspection

## **ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes**

2025-0215 - Stabilizers - Vertical Stabilizer to Rudder Junction Ribs and Lugs - Inspection / Replacement (Wrong Material)

## **ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes**

2025-0215 - Stabilizers - Vertical Stabilizer to Rudder Junction Ribs and Lugs - Inspection / Replacement (Wrong Material)

## **Boeing 737 Series Aeroplanes**

2025-19-12 - Main Landing Gear Outer Cylinders

## **Boeing 757 Series Aeroplanes**

2025-19-11 - Main Landing Gear Outer Cylinders

2025-20-04 - Aileron Trim Actuator Attachment Lug

## **Boeing 787 Series Aeroplanes**

2025-20-03 - Corrosion on Lower Fitting Assemblies and Adjacent Lavatory Components

## **Bombardier BD-700 Series Aeroplanes**

CF-2025-49 - Wings - Low Clearance Between Fuel Vent Tube Installation and Surrounding Systems and Structures in Right Wing

CF-2025-50 - Flight Controls - Roll Control Input-Modules (RCIMs) Incorrect Installation

## **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2025-51 - Flight Controls - Uncommanded and Unarrested Flap Movement

## **Dassault Aviation Falcon 7X Series Aeroplanes**

2025-0200 (correction) - Equipment / Furnishings - Passenger Seats - Modification

## **Dassault Aviation Mystere-Falcon 50 and 900 and Falcon 900EX Series Aeroplanes**

2025-0200 (correction) - Equipment / Furnishings - Passenger Seats - Modification

## **Dassault Aviation Falcon 2000 Series Aeroplanes**

2025-0200 (correction) - Equipment / Furnishings - Passenger Seats - Modification

## **Embraer EMB-135 and EMB-145 Series Aeroplanes**

2025-09-02 Correction - Revision of Airworthiness Limitations

## **Embraer ERJ 190 Series Aeroplanes**

2025-10-01 - Engine Feed Check Valve

## **Pilatus Aircraft PC-24 Series Aeroplanes**

2025-0211 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

## **Textron Aviation (Beechcraft) 300 Series Aeroplanes**

2025-20-11 - Rudder Control Pushrod Failure

## **Turbine Engines**

### **International Aero Engines AG (IAE) Turbine Engines - V2500 series**

2025-19-13 - High-Pressure Turbine 1st and 2nd Stage Hubs - Replacement