



Inappropriate packaging of EAM KSE-35L8
Life Jackets

AWB 25-028 **Issue :** 1
Date : 26 June 2014

1. Effectivity

EAM KSE-35L8 Life Jackets last maintained by M.O.S.S. Australia Pty. Ltd.

2. Purpose

To advise of inappropriately packaging of life jackets after maintenance that may affect their serviceability and/or useability.

3. Background

CASA has become aware of EAM Life Jackets that have been inappropriately packaged by M.O.S.S. Australia after Maintenance Inspections. The inappropriate packaging (valise and pull tag) can be identified by the words "M.O.S.S. AUSTRALIA PTY. LIMITED" printed on the pull tag. See Figure 1 below.



Figure 1

The valise and pull tag are an unapproved changed to the approved configuration of the Life Jacket.

This guidance is only applicable to EAM KSE-35L8 Life Jackets whose last maintenance inspection was conducted by M.O.S.S Australia Pty. Ltd. It does not affect other makes and models of Life Jackets that M.O.S.S Australia Pty. Ltd. may have serviced.

4. Recommendation

Operators with Life Jackets identified in this AWB should have them undergo a 'Non-scheduled Maintenance Inspection' by an appropriately qualified Maintenance Organisation.



AIRWORTHINESS BULLETIN

Inappropriate packaging of EAM KSE-35L8
Life Jackets

AWB 25-028 **Issue :** 1
Date : 26 June 2014

5. Reporting

Any Life Jackets found with M.O.S.S. Australia pull tags should be reported to CASA by submitting a [Service Difficulty Report](#).

6. Enquiries

Enquiries with regard to the content of this Airworthiness Bulletin should be made via the direct link e-mail address:

AirworthinessBulletin@casa.gov.au

or in writing, to:

Airworthiness and Engineering Standards Branch
Standards Division
Civil Aviation Safety Authority
GPO Box 2005, Canberra, ACT, 2601